

Operator Manual

ORBISPHERE G1100 SENSOR AND 410 INSTRUMENT



Product Recycling Information



ENGLISH

Electrical equipment marked with this symbol may not be disposed of in European public disposal systems after 12 August 2005. In conformity with European local and national regulations (EU Directive 2002/96/EC), European electrical equipment users must now return old or end-of-life equipment to the manufacturer for disposal at no charge to the user.

Note: For return for recycling, please contact the equipment manufacturer or supplier for instructions on how to return end-of-life equipment for proper disposal.

DEUTSCH

Elektrogeräte, die mit diesem Symbol gekennzeichnet sind, dürfen in Europa nach dem 12. August 2005 nicht mehr über die öffentliche Abfallentsorgung entsorgt werden. In Übereinstimmung mit lokalen und nationalen europäischen Bestimmungen (EU-Richtlinie 2002/96/EC), müssen Benutzer von Elektrogeräten in Europa ab diesem Zeitpunkt alte bzw. zu verschrottende Geräte zur Entsorgung kostenfrei an den Hersteller zurückgeben.

Hinweis: Bitte wenden Sie sich an den Hersteller bzw. an den Händler, von dem Sie das Gerät bezogen haben, um Informationen zur Rückgabe des Altgeräts zur ordnungsgemäßen Entsorgung zu erhalten.

FRANCAIS

A partir du 12 août 2005, il est interdit de mettre au rebut le matériel électrique marqué de ce symbole par les voies habituelles de déchetterie publique. Conformément à la réglementation européenne (directive UE 2002/96/EC), les utilisateurs de matériel électrique en Europe doivent désormais retourner le matériel usé ou périmé au fabricant pour élimination, sans frais pour l'utilisateur.

Remarque: Veuillez vous adresser au fabricant ou au fournisseur du matériel pour les instructions de retour du matériel usé ou périmé aux fins d'élimination conforme.

ITALIANO

Le apparecchiature elettriche con apposto questo simbolo non possono essere smaltite nelle discariche pubbliche europee successivamente al 12 agosto 2005. In conformità alle normative europee locali e nazionali (Direttiva UE 2002/96/EC), gli utilizzatori europei di apparecchiature elettriche devono restituire al produttore le apparecchiature vecchie o a fine vita per lo smaltimento senza alcun costo a carico dell'utilizzatore.

Nota: Per conoscere le modalità di restituzione delle apparecchiature a fine vita da riciclare, contattare il produttore o il fornitore dell'apparecchiatura per un corretto smaltimento.

DANSK

Elektriske apparater, der er mærket med dette symbol, må ikke bortskaffes i europæiske offentlige affaldssystemer efter den 12. august 2005. I henhold til europæiske lokale og nationale regler (EU-direktiv 2002/96/EF) skal europæiske brugere af elektriske apparater nu returnere gamle eller udtjente apparater til producenten med henblik på bortskaffelse uden omkostninger for brugeren.

Bemærk: I forbindelse med returnering til genbrug skal du kontakte producenten eller leverandøren af apparatet for at få instruktioner om, hvordan udtjente apparater bortskaffes korrekt.

SVENSKA

Elektronikutrustning som är märkt med denna symbol kanske inte kan lämnas in på europeiska offentliga sopsstationer efter 2005-08-12. Enligt europeiska lokala och nationella föreskrifter (EU-direktiv 2002/96/EC) måste användare av elektronikutrustning i Europa nu återlämna gammal eller uttrangerad utrustning till tillverkaren för kassering utan kostnad för användaren.

Obs! Om du ska återlämna utrustning för återvinning ska du kontakta tillverkaren av utrustningen eller återförsäljaren för att få anvisningar om hur du återlämnar kasserad utrustning för att den ska bortskaffas på rätt sätt.

ESPAÑOL

A partir del 12 de agosto de 2005, los equipos eléctricos que lleven este símbolo no deberán ser desechados en los puntos limpios europeos. De conformidad con las normativas europeas locales y nacionales (Directiva de la UE 2002/96/EC), a partir de esa fecha, los usuarios europeos de equipos eléctricos deberán devolver los equipos usados u obsoletos al fabricante de los mismos para su reciclado, sin coste alguno para el usuario.

Nota: *Sírvase ponerse en contacto con el fabricante o proveedor de los equipos para solicitar instrucciones sobre cómo devolver los equipos obsoletos para su correcto reciclado.*

NEDERLANDS

Elektrische apparatuur die is voorzien van dit symbool mag na 12 augustus 2005 niet meer worden afgevoerd naar Europese openbare afvalsystemen. Conform Europese lokale en nationale wetgeving (EU-richtlijn 2002/96/EC) dienen gebruikers van elektrische apparaten voortaan hun oude of afgedankte apparatuur kosteloos voor recycling of vernietiging naar de producent terug te brengen.

Nota: *Als u apparatuur voor recycling terugbrengt, moet u contact opnemen met de producent of leverancier voor instructies voor het terugbrengen van de afgedankte apparatuur voor een juiste verwerking.*

POLSKI

Sprzęt elektryczny oznaczony takim symbolem nie może być likwidowany w europejskich systemach utylizacji po dniu 12 sierpnia 2005. Zgodnie z europejskimi, lokalnymi i państwowymi przepisami prawa (Dyrektywa Unii Europejskiej 2002/96/EC), użytkownicy sprzętu elektrycznego w Europie muszą obecnie przekazywać Producentowi stary sprzęt lub sprzęt po okresie użytkowania do bezpłatnej utylizacji.

Uwaga: *Aby przekazać sprzęt do recyklingu, należy zwrócić się do producenta lub dostawcy sprzętu w celu uzyskania instrukcji dotyczących procedur przekazywania do utylizacji sprzętu po okresie użytkowania.*

PORTUGUÊS

Qualquer equipamento eléctrico que ostente este símbolo não poderá ser eliminado através dos sistemas públicos europeus de tratamento de resíduos sólidos a partir de 12 de Agosto de 2005. De acordo com as normas locais e europeias (Directiva Europeia 2002/96/EC), os utilizadores europeus de equipamentos eléctricos deverão agora devolver os seus equipamentos velhos ou em fim de vida ao produtor para o respectivo tratamento sem quaisquer custos para o utilizador.

Nota: *No que toca à devolução para reciclagem, por favor, contacte o produtor ou fornecedor do equipamento para instruções de devolução de equipamento em fim de vida para a sua correcta eliminação.*

Product Disposal

Note:

The following only applies to European customers.

Hach Ultra is committed to ensuring that the risk of any environmental damage or pollution caused by any of its products is minimized as far as possible. The European Waste Electrical and Electronic Equipment (WEEE) Directive (2002/96/EC) that came into force on August 13 2005 aims to reduce the waste arising from electrical and electronic equipment; and improve the environmental performance of all those involved in the life cycle of electrical and electronic equipment.



In conformity with European local and national regulations (EU Directive 2002/96/EC stated above), electrical equipment marked with the above symbol may not be disposed of in European public disposal systems after 12 August 2005.

Hach Ultra will offer to take back (**free of charge to the customer**) any old, unserviceable or redundant analyzers and systems which carry the above symbol, and which were originally supplied by Hach Ultra. Hach Ultra will then be responsible for the disposal of this equipment.

In addition, Hach Ultra will offer to take back (**at cost to the customer**) any old, unserviceable or redundant analyzers and systems which do not carry the above symbol, but which were originally supplied by Hach Ultra. Hach Ultra will then be responsible for the disposal of this equipment.

Should you wish to arrange for the disposal of any piece of equipment originally supplied by Hach Ultra, please contact your supplier or our After Sales Service department in Geneva for instructions on how to return this equipment for proper disposal.

Restriction of Hazardous Substances

Note:

The following only applies to exports of the product into the People's Republic of China.

Marking 标记



Products contain toxic or hazardous substances or elements.
含有有毒或者危险物质及成分的产品。

Environment Protection Use Period Marking (years).
环保使用期限标记 (年)

Toxic or Hazardous Substances and Elements 有毒或者危险物质和成分						
Part Name 部件名称	Lead (Pb) 铅	Mercury (Hg) 汞	Cadmium (Cd) 镉	Hexavalent Chromium (Cr VI) 六价铬	Polybrom Biphenyls (PBB) 多溴联苯	Polybrom Diphenyls (PBDE) 多溴联苯醚
1153 Board	X					
1154 Board	X					
1167 Board	X					
1168 Board	X					
Locking System	X					
Spacer	X					
External Connectors	X					
Sensor Head	X					
O: Indicates that this toxic or hazardous substance contained in all homogeneous material for this part is below the limit requirement 表示所有此类部件的材料中所含有毒或危险物质低于限制要求 X: Indicates that this toxic or hazardous substance contained in at least one of the homogeneous materials used for this part is above the limit requirement 表示至少有一种此类部件材料中所含有毒或危险物质高于限制要求						

Table of Contents

1 Installation

1.1	Unpacking.....	9
1.2	Installation Check List.....	9
1.3	Wall Mount and Pipe Mount Instruments.....	10
1.3.1	Instrument Dimensions.....	10
1.3.2	Wall Mounting.....	11
1.3.3	Pipe Mounting.....	11
1.3.4	Connections (bottom of instrument)	12
1.4	Panel Mount Instrument	13
1.4.1	Instrument Dimensions.....	13
1.4.2	Mounting.....	14
1.4.3	Connections (bottom of instrument)	15
1.5	Connectors Assembly Instructions	16
1.5.1	Cable Gland Wiring Instructions	16
1.5.2	USB-B Client Adapter Cable	17
1.6	Connection to Mains Power Supply.....	17
1.6.1	Power Supply Connection (low voltage instruments)	17
1.6.2	Power Supply Connection (high voltage instruments).....	18
1.7	Connections to Electronic Boards	19
1.7.1	Electronic Boards Connectors	19
1.7.2	Main Board Connections	19
1.7.3	Measurement Board	20
1.8	Measurement Alarm Relays	20
1.9	Sensor Installation	21
1.9.1	Instrument Connections.....	21
1.9.2	Flow Chamber	22
1.9.3	Flow Rate	23
1.9.4	Calibration Gas.....	23

2 User Interface

2.1	Instrument.....	25
2.2	Touch Screen	25
2.2.1	Function Keys on the Header Bar	26
2.2.2	Menu Navigation.....	27
2.2.3	Rolling List	27
2.2.4	Virtual Keyboard	27
2.2.5	Identification and Authorization Level.....	28
2.2.6	Warning Windows.....	28
2.3	Main Menu Structure	29

3 View Menu

3.1	Selection of the View Style	32
3.1.1	Numeric View	32

3.1.2	Diagnostic View	32
3.1.3	Statistic View.....	32
3.2	Configuration of the View Styles	34
3.2.1	Numeric View Configuration	34
3.2.2	Statistic View Configuration	34
4	Measurement Menu	
4.1	Instrument Configuration	35
4.2	Measurement Configuration	36
4.2.1	Measurement Alarms Configuration	36
4.2.2	Measurement Filter Configuration.....	37
4.3	Measured Data Storage.....	38
5	Calibration Menu	
5.1	Sensor Calibration	40
5.1.1	Initial Sensor Calibration	40
5.1.2	Automatic Calibration.....	41
5.1.3	Manual Calibration	41
5.2	Calibration Configuration	42
5.2.1	Configure Automatic Calibration	43
5.2.2	Configure Manual Calibration	43
5.2.3	Zero Calibration	44
5.2.4	High-Level Adjustment.....	45
5.3	Sensor Verification.....	45
5.4	Barometric Pressure Calibration	45
5.5	Calibration Reports	46
6	Inputs/Outputs Menu	
6.1	Configure Snooze	47
6.2	View Inputs/Outputs.....	48
6.3	Relays.....	48
6.3.1	Relay Configuration	48
6.3.2	Test Channel Relays.....	49
6.3.3	Test System Relay.....	49
6.4	Analog Output.....	50
6.4.1	Instrument Configuration.....	51
6.4.2	Channel Configuration	52
6.4.3	Calibration.....	54
6.4.4	Direct Test.....	55
6.4.5	Characteristics Test	55
6.5	Analog Output Characteristics	56
6.5.1	“Linear” Analog Output.....	56
6.5.2	“Tri-linear” Analog Output	57
6.5.3	“None” Analog Output	58
7	Communication Menu	

7.1	RS-485 Simple Mode Configuration	60
7.1.1	Data Available	61
7.1.2	Example of Use	64
7.2	PROFIBUS-DP Communication (optional)	65
7.2.1	Installation	65
7.2.2	Input/Output Data	66
7.3	USB-A Port (host)	70
7.4	HTTP/TCP-IP	70
7.4.1	Overview	70
7.4.2	PC Interface	71
7.5	Data File Transfer Through the USB-B Port (client)	73
7.5.1	PC Software Installation	73
7.5.2	Microsoft ActiveSync® Configuration	74
7.5.3	Upload Report Files	75

8 Security Menu

8.1	Access Rights Management	78
8.2	Configure Security	78
8.3	User Management	79
8.4	User Action Log File	79

9 Products Menu

9.1	Overview	81
9.1.1	Select Product	82
9.1.2	Modify Product	82

10 Global Configuration Menu

10.1	Overview	83
10.1.1	Save	83
10.1.2	Select	83

11 Services Menu

11.1	Sensor Diagnostics	87
11.1.1	Calibration Timer	87
11.1.2	Service Timer	87
11.2	Language Selection	87
11.3	Clock	88
11.4	Screen	88
11.4.1	Screen Calibration	88
11.4.2	Screen Contrast	88
11.5	Buzzer	88
11.6	Boards Info	89
11.6.1	Main Board Info	89
11.6.2	Measurement Board Info	89
11.6.3	Sensor Parameters	89
11.7	Batteries	90

11.8	Software Download.....	90
11.9	End Application.....	90

12 Maintenance and Troubleshooting

12.1	Instrument Maintenance	91
12.2	Sensor Maintenance.....	91
12.2.1	Equipment Required	91
12.2.2	Sensor Spot Removal.....	91
12.2.3	Sensor Spot Replacement.....	92
12.3	Storage, Handling and Transportation.....	92
12.4	Troubleshooting	93
12.5	List of Events and Alarms	94

13 Specifications

13.1	General Principle of Operation	95
13.2	Hardware Description	96
13.3	Model Identification System.....	97
13.4	Operating Conditions	98
13.5	Measurement.....	98
13.6	Power Supply.....	98
13.7	Communication.....	98
13.8	Size and Weight.....	99
13.9	Analog and Digital Outputs	99
13.10	Security Level Table	100
13.11	Default Parameters.....	101

14 Part Lists

14.1	Accessories and Spare Parts	103
14.2	Instrument Options	104

Appendix A: Glossary

A.1	Gas Units.....	105
A.2	Generic Terms and Definitions	106

Manual Overview

About this Manual

The information in this manual has been carefully checked and is believed to be accurate. However, Hach Ultra assumes no responsibility for any inaccuracies that may be contained in this manual. In no event will Hach Ultra be liable for direct, indirect, special, incidental, or consequential damages resulting from any defect or omission in this manual, even if advised of the possibility of such damages. In the interest of continued product development, Hach Ultra reserves the right to make improvements in this manual and the products it describes at any time, without notice or obligation.

Published in Europe.

Copyright © 2007 by Hach Ultra. All rights reserved. No part of the contents of this manual may be reproduced or transmitted in any form or by any means without the written permission of Hach Ultra.

Revision History

- Revision A, October 2006, Hach Ultra
- Revision B, March 2007, Hach Ultra
- Revision C, May 2007, Hach Ultra
- Revision D, August 2007, Hach Ultra
- Revision E, September 2007, Hach Ultra

Safety Conventions



WARNING

A warning is used to indicate a condition which, if not met, could cause serious personal injury and/or death. Do not move beyond a warning until all conditions have been met.

CAUTION:

A caution is used to indicate a condition which, if not met, could cause minor or moderate personal injury and/or damage to the equipment. Do not move beyond a caution until all conditions have been met.

Note:

A note is used to indicate important information or instructions that should be considered before operating the equipment.

Safety Recommendations

For safe operation, please read the entire manual before unpacking, setting up, or operating this instrument. Pay particular attention to all warning and caution statements. Failure to do so could result in serious injury to the operator or damage to the equipment.

To ensure the protection provided by this equipment is not impaired, do not use or install this equipment in any manner other than that which is specified in this manual.

If repairs or adjustments are necessary, the instrument should be returned to an authorized Hach Ultra service center.

**WARNING**

The installation of the instrument should be performed exclusively by personnel specialized and authorized to work on electrical installations, in accordance with relevant local regulations. Disconnect the power supply of the instrument before carrying out any work inside the instrument. In addition, and in accordance with safety standards, it must be possible to disconnect the power supply of the instrument in its immediate vicinity.

CAUTION:

Proper ESD (electrostatic discharge) protocols must be followed to prevent damage to the product. All fittings must be properly seated and tightened to prevent water and dust ingress.

**WARNING**

- *Do not connect the instrument to any electrical source that uses a 230V IT neutral regime.*
- *A bipolar circuit breaker must be installed in a 2-phase mains power supply without neutral.*
- *Always disconnect the instrument before any intervention.*
- *The power cord plug connection is also used as a main power switch.*
- *Access to the internal components of the instrument is restricted to Hach Ultra or its representatives.*
- *All external connectors, except the 4-pin POWER in the wall and panel models, are of Very Low Voltage Safety (< 50V). They should be connected only on apparatus with the same characteristics.*
- *The instrument must be connected to an electrical system which complies with applicable local regulations.*
- *All the cables connected to the instrument must be fire resistant, type UL94V-1*
- *The operator must read and understand this manual before using the instrument.*
- *The instrument will not be used as a safety device. It does not provide a security function in a hazardous process.*

Service and Repairs

None of the instrument's components can be serviced by the user. Only personnel from Hach Ultra or its approved representative(s) is (are) authorized to attempt repairs to the system and only components formally approved by the manufacturer should be used. Any attempt at repairing the instrument in contravention of these principles could cause damage to the instrument and corporal injury to the person carrying out the repair. It renders the warranty null and void and could compromise the correct working of the instrument and the electrical integrity or the CE compliance of the instrument.

If you have any problems with installation, starting, or using the instrument please contact the company that sold it to you. If this is not possible, or if the results of this approach are not satisfactory, please contact the manufacturer's Customer Service.

Intended Use of this Equipment

This high accuracy Orbisphere instrument is designed for the measurement of dissolved oxygen in water in applications such as beverage, life sciences, power generation, and the electronics industry.

Orbisphere 410 analyzers are available as wall or pipe mount, and rack mount versions. This version of the instrument uses a luminescent dissolved oxygen sensor to determine the dissolved oxygen concentration in the water sample.

Precautionary Labels

Read all labels and tags attached to the instrument. Personal injury or damage to the instrument could occur if not observed.

	This symbol, when noted on a product enclosure or barrier, indicates that a risk of electrical shock and/or electrocution exists and indicates that only individuals qualified to work with hazardous voltages should open the enclosure or remove the barrier.
	This symbol, when noted on the product, indicates that the marked item can be hot and should not be touched without care.
	This symbol, when noted on the product, indicates the presence of devices sensitive to electrostatic discharge and indicates that care must be taken to prevent damage to them.
	This symbol, when noted on the product, identifies a risk of chemical harm and indicates that only individuals qualified and trained to work with chemicals should handle chemicals or perform maintenance on chemical delivery systems associated with the equipment.
	This symbol, if noted on the product, indicates the need for protective eye wear.
	This symbol, when noted on the product, identifies the location of the connection for protective earth (ground).
	Electrical equipment marked with this symbol may not be disposed of in European public disposal systems. In conformity with European local and national regulations, European electrical equipment users must now return old or end-of-life equipment to the manufacturer for disposal at no charge to the user.
	Products marked with this symbol indicates that the product contains toxic or hazardous substances or elements. The number inside the symbol indicates the environmental protection use period in years.

Acknowledgements

- Dacron, Delrin, Tedlar, Tefzel, and Viton are registered trademarks of DuPont.
- Halar is a registered trademark of Ausimont U.S.A., Inc.
- Hastelloy is a registered trademark of Haynes International.
- Kynar is a registered trademark of The Pennwalt Corporation.
- Monel is a registered trademark of IMCO Alloys International, Inc.
- Saran is a registered trademark of Dow Chemical Co.
- Swagelok is a registered trademark of Swagelok Co.
- Microsoft and Windows are registered trademarks of Microsoft Corporation.

1 Installation



WARNING

This section provides necessary information to install and connect the instrument. The installation of the instrument should be performed exclusively by personnel specialized and authorized to work on electrical installations, in accordance with relevant local regulations. Disconnect the power supply of the instrument before carrying out any work inside the instrument. In addition, and in accordance with safety standards, it must be possible to disconnect the power supply of the instrument in its immediate vicinity.

CAUTION:

Proper ESD (electrostatic discharge) protocols must be followed to prevent damage to the product. All fittings must be properly seated and tightened to prevent water and dust ingress.

1.1 Unpacking

Remove carefully the instrument and its accessories from the box and packing material, referring to the packing list included to confirm that everything has been delivered.

Please visually inspect the instrument for shipping damage. If anything is missing or damaged, contact the manufacturer or your dealer immediately.

You may want to retain the box and other packing material in case later you need to ship the instrument (see [“Storage, Handling and Transportation” on page 92](#)). Please dispose safely and ecologically of the box and packing material (if not stored for future use).

Please read through this manual thoroughly before carrying out the installation.

1.2 Installation Check List

For a complete installation, proceed to the following actions following the instructions in this manual very carefully:

- 1) Install the 410 analyzer ([section 1.3 on page 10](#) through [section 1.6 on page 17](#))
- 2) Connect the G1100 sensor to the instrument ([section 1.9.1 on page 21](#))
- 3) Attach the sensor to the flow chamber and connect the flow chamber to the sample flow, ensuring the sample outlet is directed to drain/waste ([section 1.9.2 on page 22](#))
- 4) Connect the calibration gas bottle ([section 1.9.4 on page 23](#)) ensuring the purity of the nitrogen gas is 99.999% or better
- 5) Turn the instrument on and set the operating language ([section 11.2 on page 87](#))
- 6) Set the security levels, users ID's and passwords ([section 8 on page 77](#))
- 7) If measuring in gas phase with fraction units (% , ppm), perform a barometric sensor calibration ([section 5.4 on page 45](#))
- 8) Perform an initial gas sensor calibration using the manual zero calibration with auto-end enabled ([section 5.1.1 on page 40](#))
- 9) Enable the auto-calibration feature ([section 5.2 on page 42](#)) and set the auto calibration frequency ([section 5.2.1 on page 43](#))

The instrument should now be ready for operation. If a problem should arise, please refer initially to [“Troubleshooting” on page 93](#). If the difficulty cannot be overcome, please contact your Hach Ultra representative who will be happy to assist you.

1.3 Wall Mount and Pipe Mount Instruments

1.3.1 Instrument Dimensions





Fig 1-1: Wall/Pipe Mount Instrument Dimensions (in millimeters)

1.3.2 Wall Mounting



Attach the U bracket (provided) to the wall with two screws (not provided).




Tilt the instrument slightly backwards to align the bracket pins and the insertion slots, and slide the instrument onto the bracket as shown.

Insert the 2 locking screws with washers through the side slots.

Adjust instrument angle for better screen vision, and lock both side screws.

Fig 1-2: Wall Mount Bracket

1.3.3 Pipe Mounting



Assemble the pipe mount bracket to the U-bracket, using the two screws provided



Attach this assembly to the pipe using two clamps (not provided) as shown on the left

The rest of the procedure is similar to the wall mount version, pictured above.

Slide the instrument onto the bracket.

Insert the 2 locking screws with washers through the side slots.

Adjust the instrument angle for better screen vision, and lock both side screws.

Fig 1-3: Pipe Mount Diagram

1.3.4 Connections (bottom of instrument)

A square key is provided to open the instrument front panel door lock. The lock is located on the right side of the instrument bottom panel (indicated with the number 10 in Fig 1-4 below).

The front panel can then be easily pivoted to the left as shown below. To retain the instrument waterproof tightness, make sure the seal is clean and in good condition before closing the front panel.




Fig 1-4: Wall and Pipe Mount Connection Panel

- | | |
|--|---|
| 1) Power cable. The type of connection will vary depending on the instrument specification (see “Connection to Mains Power Supply” on page 17) | 5) Sensor - red cable connection |
| 2) USB-B client 4 pin connector. Use the adapter cable (see “USB-B Client Adapter Cable” on page 17) | 6) Sensor - blue cable connection |
| 3) Ethernet cable gland | 7) USB-A host connector for mass storage device |
| 4) Sensor - temperature connection (black cable) | 8) External pressure sensor connection |
| | 9) Flow chamber solenoid valve connection |
| | 10) Input/Output 2 cable gland |
| | 11) Input/Output 1 cable gland |
| | 12) Keylock |

1.4 Panel Mount Instrument

1.4.1 Instrument Dimensions




Fig 1-5: Panel Mount Instrument Dimensions (in millimeters)

1.4.2 Mounting




Fig 1-6: Panel Mount Bracket Frame

- 1) Cut an opening in the panel to accommodate the bracket frame provided (this is the same size as previous generations of Orbisphere type 3600 instruments).






Fig 1-7: Opening Dimensions

- 2) Install the provided frame in the opening
- 3) Fold the 6 tabs over the panel lips, using adjustable joint pliers.
- 4) Slide the instrument in the bracket frame. The instrument should go over the four "T" pins. Rotate the 4 fast locking screws on both sides of the front panel and slide it in.
- 5) Rotate the 4 fast locking screws 1/4 turn twice in the lock direction as indicated on the side of the front panel. This locks the instrument in place on the four "T" pins.
- 6) To access the connections inside the instrument, remove the instrument housing (six screws on the back panel, and slide the housing back out)
- 7) Pass the cables through the housing, then through the cable gland (if applicable) and then perform the connections as detailed below.



CAUTION:


Do not forget to pass the cable through the housing before passing it through the cable gland on the back panel.

Alternative Instrument Mounting Procedure

When it is not convenient to work from the back of the panel, the instrument can be connected before fitting in the panel.

- 1) Install the panel support frame in the panel opening
- 2) Slip the cables through the panel opening
- 3) Remove the instrument cover
- 4) Slip the cables through the instrument cover
- 5) Slip the cables through the instrument back panel cable glands
- 6) Connect the cables to the instrument electronic boards
- 7) Tighten the cable glands
- 8) Reinstall the instrument cover
- 9) Install the instrument in the panel opening

1.4.3 Connections (bottom of instrument)




- | | |
|--|--|
| <ol style="list-style-type: none"> 1) Power cable. The type of connection will vary depending on the instrument specification (see "Connection to Mains Power Supply" on page 17) 2) Ethernet cable gland 3) USB-A host connector for mass storage device 4) USB-B client 4 pin connector. Use the adapter cable (see "USB-B Client Adapter Cable" on page 17) | <ol style="list-style-type: none"> 5) Sensor - blue cable connection 6) Sensor - red cable connection 7) Sensor - temperature connection (black cable) 8) Input/Output 2 cable gland 9) Input/Output 1 cable gland 10) Flow chamber solenoid valve connection 11) External pressure sensor connection |
|--|--|

Fig 1-8: Panel Mount Connection Panel

1.5 Connectors Assembly Instructions

1.5.1 Cable Gland Wiring Instructions


A waterproof cable gland is provided each time a cable must be connected inside the instrument. The nickel-plated brass cable glands are EMC-types, designed so that the cable shields attach directly to the instrument housing as a ground. Typical cable wiring instructions are detailed below.




Gland parts (washers not shown):

- 1) Nut
- 2) Rubber gasket (seal)
- 3) Gland fitting with O-ring (attached to instrument housing)

- 1) Unscrew the cable gland nut. Inside, the assembly is composed of a rubber gasket, and two metal washers. Note that the ethernet gland on panel and wall mount instruments does not have washers and the gasket is cut.
- 2) If wiring a sensor cable, the cable has already been prepared so simply remove the piece of plastic protection from the exposed shielding
For other cables, strip off external insulation as required, and 25 mm of shielding. Strip the wires about 8 mm from their ends (see illustration below)



- 3) Pass the cable through the nut, the rubber gasket, and the two washers
- 4) Pinch the shield so that its entire circumference is pressed between the two washers and pass the cable into the housing, blocking the cable gland



WARNING

It is vitally important to ensure the shielding is pinched and secured between the two washers to ensure the shielding attaches directly to the instrument housing as a ground. Failure to do this could cause damage to the instrument, and for sensor cables give incorrect readings.

- 5) Reattach and tighten the cable gland nut
- 6) Attach the wires to the corresponding terminal block connections

1.5.2 USB-B Client Adapter Cable



Fig 1-9: USB-B Adapter Cable

This supplied cable can be used to connect the instrument to a PC.

Connect to the instrument, and connect the USB connector to the USB outlet on the user's PC.

1.6 Connection to Mains Power Supply

1.6.1 Power Supply Connection (low voltage instruments)

For low voltage instruments (10-30 VDC), connection to the mains power supply is with an 8-pin FIXCON® connector (supplied). Connect this to the power cable as per the following instructions.


Note:

The earth wire must be longer than the other wires.



Fig 1-10: FIXCON® Connector

Pin Connections:



1+6+7) power 10-30 VDC

2+3+4) ground

8) earth

5) unused

Note:

Bridge the power and ground pins to distribute load on three pins.

1.6.2 Power Supply Connection (high voltage instruments)

High voltage instruments (100-240 VAC) are pre-wired in the instrument for mains connection with a male BINDER connector. A female connector is supplied already attached to the male connector as illustrated below.



User-supplied power cable specifications:

- 3-wire (live, neutral and earth)
- cable $\varnothing \geq 7\text{mm}$; $\leq 9.5\text{mm}$
- wire selection $\geq 1\text{mm}^2$, AWG18; $\leq 2.5\text{mm}^2$, AWG14




WARNING


Before wiring the connector, ensure the user-supplied power cable is not connected to the mains power supply.

Wire the female connector as follows:

- 1) First unscrew the female connector from the male and ease the two apart.



- 2) Take the narrow end of the connector (4) in one hand and the main body (2) in the other and unscrew the two. Pull away the cable clamp (3) and unscrew the end plug (1) to reveal the four parts that make up the connector.
- 3) Pass the user-supplied power cable (see specifications above) through the end plug (1) and the main body (2). Wire the four pins as follows:



1) Live (brown)

2) Neutral (blue)

3) Not used



Earth (green and yellow)

Note:

The numbers and earth symbol are stamped on the end of the connector. Ensure it is connected correctly.

- 4) Slide the cable clamp (3) back onto the connector (4) and secure the cable.
- 5) Screw the two parts (4) and (2) back together.
- 6) Secure the power cable by screwing the end plug (1) back in place.
- 7) Push the male and female connectors back together and screw finger tight to secure. The two connectors are grooved to avoid an incorrect fitting.

1.7 Connections to Electronic Boards

Note:

Any loose connection wires should be bundled tightly together with the use of nylon cable ties.

1.7.1 Electronic Boards Connectors

Connectors P8 on the main board (Fig 1-11) and J7 on the measurement board (Fig 1-14) are made of two parts. Push down carefully the black levers on either side of the connector and pull it out securely. Perform all connections with these connectors unplugged. Once finished, attach the connectors to the boards by pushing them firmly in place (levers up).

1.7.2 Main Board Connections




Fig 1-11: Main Board




Fig 1-12: Connector P8




Fig 1-13: Connector P3

Connector P8

- | | |
|-----------------------------|---------------------------------|
| 1) RS-485 (signal A) | 8) Not used |
| 2) RS-485 (signal B) | 9) Not used |
| 3) PROFIBUS-DP (GND) | 10) Not used |
| 4) PROFIBUS-DP (+ 5 V) | 11) System alarm relay (N.O.) |
| 5) PROFIBUS-DP (signal -) | 12) System alarm relay (N.C.) |
| 6) PROFIBUS-DP (signal +) | 13) System alarm relay (Common) |
| 7) PROFIBUS-DP (signal RTS) | |

Connector P3

Ethernet RJ 45. Connect the instrument to the local network by passing an ethernet cable through the ethernet cable gland (gland location illustrated in Fig 1-4 on page 12 for the wall mount and Fig 1-8 on page 15 for the panel mount) and connecting to the P3 connector illustrated above.

1.7.3 Measurement Board




Fig 1-14: Measurement Board




Fig 1-15: Connector J7

Connector J7 (inputs & outputs)

Measurement alarms relays

- 1) Common
- 2) Output relay 1
- 3) Output relay 2
- 4) Output relay 3

Analog current (or voltage) outputs

- 5) GND
- 6) Output 1
- 7) Output 2
- 8) Output 3

Digital inputs

- 9) Not used
- 10) Not used
- 11) Not used

- 12) Not used
- 13) Not used
- 14) Not used
- 15) Not used
- 16) Not used

1.8 Measurement Alarm Relays




Fig 1-16: Output Relays

The three output relays are located on the measurement board.

They can be individually configured to Normally Open (NO) or to Normally Closed (NC) by physically moving the jumper on each relay. On the picture example on the left:

- Upper relay is set to NC
- Middle relay is set to NO
- Lower relay is shown with no jumper

Note:

J4 (upper relay) is relay 1
J5 (middle relay) is relay 2
J6 (lower relay) is relay 3

1.9 Sensor Installation

1.9.1 Instrument Connections

The sensor determines the dissolved oxygen concentration in a given water sample. The sensor spot is coated with a luminescent material. Blue light is then transmitted to the sensor surface and red light received in return. The cables through which this light is transmitted/received are color coded.

Ensure the correct colored cable is attached to the similarly colored connector on the instrument as illustrated in [Fig 1-17](#) below for the wall mount version of the instrument. The third sensor cable (temperature - colored black) is connected to the temperature socket.




Fig 1-17: Sensor Cables Attached to a Wall Mount Instrument

Refer also to the illustration of the connector panels in [Fig 1-4 on page 12](#) for the wall and pipe mount instruments and in [Fig 1-8 on page 15](#) for panel instruments.

1.9.2 Flow Chamber

Attach the sensor to the specially designed flow chamber (illustrated in [Fig 1-18 on page 22](#)). To do this, pull the sensor locking screw up (No. 9 in the illustration) and then gently position the sensor into the flow chamber. Push down on the locking screw and make a couple of turns until the sensor is secure. Then release the sensor and finger tighten the locking device to the flow chamber. Do not overtighten as this could damage the threads.

Next, ensure the solenoid valve is correctly connected to the instrument (as illustrated in [Fig 1-17](#) above for the wall mount instrument). This valve is used to turn the sample flow off during calibration to allow the calibration gas to flow over the sensor surface.

Connect the sample flow to the sample inlet socket (6). The sample outlet (5) should go directly to drain/waste to avoid any back pressure during the sensor calibration process. For these connections, use a wrench to securely hold the nut attached to the flow chamber, and a second wrench to tighten the swagelock connector from the sample. Do **not** tighten the connector attached to the flow chamber.





Fig 1-18: Flow Chamber Dimensions and Components

1. Active Luminescent Spot	6. Sample Inlet
2. Optical Fiber Cable	7. Calibration Gas Inlet
3. Sensor Body	8. Flow Chamber
4. Solenoid Valve	9. Sensor Locking Screw
5. Sample Outlet	

1.9.3 Flow Rate

The flow rate is dependant on the water pressure in the sample flow line. The following graph illustrates the expected flow rate through the flow chamber after installation:



1.9.4 Calibration Gas



A bottle of N_2 calibration gas should be connected to the flow chamber as illustrated left.

Connect the bottle to the calibration gas inlet socket (7) with plastic tubing. Use the supplied pressure reducer (part number 33015) on the calibration bottle.

Fully open the valve on the pressure reducer. Doing this will give the required calibration gas flow rate of 0.1 L/min.

The bottle itself is not supplied and must be purchased locally. For accurate calibrations, the calibration gas bottles must be of 99.999% (50) quality or better, with a 5/8-18 UNF (C10) fitting. A minimum of 20 liters is required (34 is recommended), with a maximum of 70 bars.

2 User Interface

2.1 Instrument

The instrument front panel provides these user interfaces:

- Touch screen acting as display, touch pad and keyboard. Contrast can be adjusted.
- LED, showing when the instrument is on.
- Buzzer which sounds each time the screen is touched, and when an event alarm is set. Sound level and type can be adjusted.

Turning Instrument On and Off

There is no power switch on the instrument. The mains must be disconnected to turn the instrument off. The LED indicates when the instrument is on.

Measurement window

The main (numeric) measurement window continuously displays:

- Sensor numeric values
- Measured sensor trends (for the last 10 minutes to last hour)
- Measured sensor data alarm limits and other events
- Temperature

2.2 Touch Screen

The user interface on the front panel is a 320x240 pixels display with touch screen. To make navigation user friendly, the interface software is Windows CE based, providing easy selection through menus.




Fig 2-1: Numeric View

All the measurement, configuration, calibration and "standard service" routines can be called by pressing buttons and menu bars on screen.

Measurement display shows one measurement slope.

Display can be configured to only show a sensor measurement, or to show a parametrized graphic representation of the last measurements.

Touching some items on the display calls a related function, similar to a shortcut.

2.2.1 Function Keys on the Header Bar

Shortcut to the user login window. Pressing this button for more than 2 seconds calls the ID and password window (see [“Identification and Authorization Level” on page 28](#)).



- Closed padlock indicates that the touch screen is locked.
- Open padlock indicates that the instrument is in view mode only, but no user is logged in (level 0).
- When a user is logged in, this box shows the authorization level of this user as 1, 2, 3 or 4 (4 being the highest, see [“User Management” on page 79](#)).




This icon is used for adjusting the display contrast to improve visibility. It is available all the time to any user, regardless of the user security level. This icon is a shortcut to the contrast adjustment window. See [“Screen Contrast” on page 88](#)




Short cut to the data storage window. Number shows the number of measurement currently stored in volatile memory.

- No storage
- Store at once: When the buffer is full (1,000 positions), the recording of measurement stops.
- Rolling buffer: When the buffer is full, the latest measurement set replaces the oldest one (first-in, first-out)



normal - snooze


In the event of an alarm, the “snooze” button stops the instrument buzzer and returns all the relays in the instrument to their normal state during the “snooze time”. The icon indicates if the alarms is on “snooze” or not. This “snooze” is configurable (see [“Configure Snooze” on page 47](#)).



Current date and time. This is also a shortcut to the date and time setting window.



Call the contextual menu. This menu is in the header bar and its content is related to the view displayed.



Opens the main menu page for easy navigation through all available menus.

2.2.2 Menu Navigation





Fig 2-2: Main Menu Window

Pressing the “menu” button in the header bar calls the main menu. The display is made of three columns:


- The left column is the menus, or submenus (greyed out options are not available)
- The center column shows a tree view of actual position inside the menu structure
- The right column has the generic controls detailed below.




Return to previous menu (one step back)



Jump directly to main menu



Close the menu and go back to measurement view display. If the menu button is pressed again, the menu returns to its previous state (tree structure is saved)



Help topics concerning current menu

2.2.3 Rolling List




Fig 2-3: Rolling List Example

For convenience, selection through a possible large list of items has been designed with a rolling list, like in this example. Use the up and down arrow to navigate, or select directly one item and press OK.

2.2.4 Virtual Keyboard




Fig 2-4: Virtual Editing Keyboard

When a text box (alphanumeric field) has to be edited and is pressed, a virtual keyboard appears on screen. It can be used as a PC keyboard (pressing CAP gives access to special keys).

Once values have been entered, press the “ENTER” key to confirm and exit the virtual keyboard.

During the editing, the edited field name is displayed, along with units where applicable.

2.2.5 Identification and Authorization Level

Once the access rights have been set, ([See “User Management” on page 79](#)) it is necessary to log in as an authorized user to get access to the instrument functionalities and settings.




Fig 2-5: Identification Window

Press the closed padlock  for two seconds to open the identification window. The user identification and password must be entered to access functionalities authorized by the security level of the given user (5 levels available. [See “User Management” on page 79](#)).

For security, when the session inactivity delay period has expired (adjustable, via [“Configure Security” on page 78](#)), the user is logged off automatically.

Note:
To get to level 0, press the unlock button and OK, without entering any ID or password.

2.2.6 Warning Windows




Fig 2-6: Warnings

At various stages, a warning message may be displayed to request confirmation from the operator that his last action(s) must really be saved or cleared, or that there is a problem that did not enable the requested action, such as during instrument calibration (example shown left).

2.3 Main Menu Structure

This is the structure of the main menu which is used to control every functionality of the instrument. These submenus are detailed in the following sections of this Operator Manual.



Fig 2-7: Main Menu Structure

3 View Menu





Fig 3-1: View Menu

3.1 Selection of the View Style


3.1.1 Numeric View



This is the default view: Display shows the numeric measurement value identified for the gas measurement channel, a graphic showing measurement value evolution during the set time frame, and sample temperature.


This display can be configured to suit individual conditions and convenience.

3.1.2 Diagnostic View



The diagnostic view contains useful information for troubleshooting purposes.

3.1.3 Statistic View



This feature offers statistical data that matches with Total Quality management tools. Statistics is a tool to better analyze how a process behaves. The 410 statistics window gives some useful information.

The statistics are calculated from the data in the measurement file. The values are updated each time a new value is added to this file. Therefore the changes made in the configuration window are considered only once a new value is added.

Cp process capability

Cp is an index used to assess the width of the process spread in comparison to the width of the specification. It is calculated by dividing the allowable spread by the actual spread.

- A Cp of one indicates that the width of the process and the width of the specification are the same.
- A Cp of less than one indicates that the process spread is greater than the specification. This means that some of the data lies outside the specification.
- A Cp of greater than one indicates that the process spread is less than the width of the specification. Potentially this means that the process can fit inside the specification limits.

CPk process variability

Cpk takes into account the center of the data relative to the specifications, as well as the variation in the process.

- A Cpk value of one indicates that the tail of the distribution and the specification are an equal distance from the overall average.
- A Cpk of less than one means that some of the data is beyond the specification limit.
- A Cpk greater than one indicates that the data is within the specification.
- The larger the Cpk, the more central and within specification the data.

CPm process repeatability

Capability index that takes into account variation between the process average and the target. If the process average and the target are the same value, Cpm will be the same as Cpk. If the average drifts from the target, Cpm will be less than Cpk.




Fig 3-2: Skewness

Skewness

An asymmetric frequency distribution is skewed to the left if the lower tail is longer than the upper tail, and skewed to the right if the upper tail is longer than the lower tail. Distributions of positive-valued random variables values are often skewed right.




Fig 3-3: Kurtosis

Kurtosis

Kurtosis is a parameter that describes the shape of a random variable's probability distribution.

The graphs on the left illustrate the notion of kurtosis. The lower curve has higher kurtosis than the upper curve. It is more peaked at the center, and it has fatter tails

3.2 Configuration of the View Styles

3.2.1 Numeric View Configuration

List of parameters that can be adjusted to customize the numeric view display:

- ▼ Display temperature: no, channel temperature
- ☒ Display mini graph: yes/no
- ☒ Display time base: yes/no
- ☐ Upper bound: Adjust graph upper limit
- ☐ Lower bound: Adjust graph lower limit
- ☐ Time base: Adjust graph time span
- ⇒ Grid button: Set up the graph to display the x or y axes, the grid, or the thresholds
- ⇒ Auto Scale update: Automatically set the graph upper and lower bounds to best fit the actual values displayed.
- ⇒ Clean button: Clear the slope displayed. The slope restarts from the left side.

3.2.2 Statistic View Configuration

Scope:

- ☐ Number of values: Statistic calculation range (from 10 to 1,000 values). Number of value taken in consideration in the log file since last value stored. The recorded values with alarms are not considered for calculation, but are part of the log file.

Histogram:

- ▼ Upper limit: Select High or High High alarm value, or a custom value.
- ▼ Lower limit: Select Low or Low Low alarm value, or a custom value.

Capability:

- ▼ Upper limit: Select High or High High alarm value, or a custom value.
- ▼ Lower limit: Select Low or Low Low alarm value, or a custom value.

4 Measurement Menu





Fig 4-1: Measurement Menu

4.1 Instrument Configuration

Continuous mode description

The continuous mode is typically used for process measurement, and follows this cycle:

- Every 2 sec. measurements are refreshed on the display
- Regularly updates the outputs (relay and analog outputs)
- Continuously stores measurements in memory (volatile and non volatile memory).



- ▼ Measurement mode is locked on *Continuous* for on line processes.
- ▼ Selection of units for barometric pressure and temperature

4.2 Measurement Configuration

- ▼ Sensor's spot selection
- ▼ Medium: Liquid or gas phase.
- ▼ Gas unit type: Partial, Fraction, Dissolved.
- ▼ Gas unit *: The list of available units depends on unit type selected above.
- ▼ Liquid: When medium is liquid, select water or a liquid with a different solubility (if available).

Note:

* This is the gas concentration measured by the sensor. When a composite unit is selected (e.g. ppm → ppb) the unit will change depending on the range of the value to display.

- ▼ Display resolution: Maximum resolution depends on unit. A maximum of 5 digits can be displayed. Decimals can be limited to 0, 1, 2 or 3 decimals for easier reading. That does not affect the actual resolution of data measured and stored, but only the data displayed.
- ▼ Thermal cutoff: This option is for information purposes only. It is possible to set a sample high temperature limit, which if exceeded causes the system to display a "HOT" alarm message. It is recommended, however, to disable this function.
 - Thermal cut off options: Disabled / enabled.
 - Thermal cut off temperature: To be set according to conditions.

4.2.1 Measurement Alarms Configuration

Set the thresholds for the low/high concentration levels, according to the application. Each alarm type can be individually enabled or disabled without losing its settings.

These events can activate the relays and can be displayed.

- ☐ Low-low: 2nd stage for too low concentration
- ☐ Low: 1st stage for too low concentration
- ☐ High: 1st stage for too high concentration
- ☐ High-high: 2nd stage for too high concentration
- ☐ Hysteresis: A percentage of the above concentration values. The hysteresis is used to prevent relay "flickering" when the measurement is just at the alarm levels. Set this to a minimum, but enough to eliminate flickering.

As an example, if the High Alarm is set to 40 units and the Hysteresis is set to 10%, then the High Alarm is activated once the measurement reaches 40 units, but only deactivated once the measurement drops below 36 units. With the Low Alarm the opposite is true, in that if the Low Alarm is set to 20 units and the Hysteresis set to 10%, then the Low Alarm is activated when the measurement drops below 20 units, and deactivated when the measurement rises above 22 units.

- **Delay:** The delay in seconds, before alarms go on whenever concentration values go above "High alarms" or below "Low alarms". Set this to a minimum value, but enough to avoid alarms for non-representative peaks beyond the set level.




Fig 4-2: Alarms System Diagram

4.2.2 Measurement Filter Configuration

Measurement filter configuration

State:

Type:

Depth:

Central depth:

The filters are aimed at "flattening" the measurement curve in situations where the process shows atypical peak values that could otherwise hamper the interpretation of measurement readings. The filter is applied on the last set of measurements each time a measurement is taken.

- ▼ **Mean:** Mathematical average of the last set (depth) of measurement values.
- ▼ **Median filter:** Allows for eliminating atypical peak measurement values, and average the remaining ones. The calculation sorts the last measurements set (depth) by values, then delete the highest and lowest values, and averages the remaining values (central depth).

- Example for depth 7, central depth 5:
Sorted values, both ends eliminated, the average of the center five is then 3.88.

0.7	1.1	4.0	4.3	4.4	5.6	7.0
-----	-----	-----	-----	-----	-----	-----

- Example for depth 5, central depth 3:
Sorted values, both ends eliminated, the average of the center three is then 4.23.


1.1	4.0	4.3	4.4	5.6
-----	-----	-----	-----	-----

- Example for depth 8, central depth 4:
Sorted values, both ends eliminated, the average of the center four is then 4.43.

0.7	1.1	4.0	4.3	4.4	5	5.6	7.0
-----	-----	-----	-----	-----	---	-----	-----

4.3 Measured Data Storage

There is one measurement file which contains the data generated by the measurement cycle. The measurement file is updated in volatile memory, and regularly copied in non-volatile memory (file back-up). At start up, the measurement file in volatile memory is updated with the file from the non-volatile memory.



Note:

Data stored in volatile memory are lost when instrument is off, non-volatile memory is permanent. In case of an accidental power off event, the instrument resumes measurement storage after the last measurement stored in flash.

This dialog box allows adjustment of the parameters for recording and storing measurements.

▼ Storage mode selection:

- No storage
- Store once: When the volatile memory is full (1,000 positions), the recording of measurement stops.
- Rolling buffer: When the volatile memory is full, the latest measurement set replaces the oldest one continuously (first-in, first-out)

- ☐ RAM time (volatile memory): Delay in seconds between two recordings of measured data.
- ☐ FLASH time (non-volatile memory): Delay in seconds between two data file transfers from volatile memory into non-volatile memory. The last data file erases the previous one. This field is only available if the Auto save in flash box is checked.
- ☐ Save in flash now: Press this button to store measurement data in flash (non-volatile memory) immediately. After pressing this button, press OK to initiate the process. A warning screen appears informing you that the operation can take up to 30 seconds. Press Yes to continue with the process, or No to abort.
- ☒ Auto save in flash: Check this box to save measurements in flash (non-volatile memory) automatically. Measurements are saved at regular time intervals as defined in the FLASH time box.
- ☐ Purge data: Clear all data in the volatile and non-volatile memories
- ☐ Start logging measurement: Store once mode. Starts and stops the measurement recording session. Measurement recording is stopped when the buffer is full.
- ☐ Open data: Opens a table showing the measured values which are stored in the volatile memory (RAM).

Use the scroll bar at the right to move to another data range (the id range will be shown in the title bar).

The page number being viewed and the total number of pages are shown at the bottom (page 1 of 13 in the example left).

Use the keys at the bottom to move directly to the first page, previous page, next page or last page.

Id	mm/dd	hh:mm:ss	Gas	Temp	Mask...
644	03/01	04:32:39	2937.32	25.3	00000000
643	03/01	04:32:29	2937.31	25.3	00000000
642	03/01	04:32:19	2937.31	25.3	00000000
641	03/01	04:32:09	2937.31	25.3	00000000
640	03/01	04:31:59	2937.31	25.3	00000000
639	03/01	04:31:49	2937.31	25.3	00000000
638	03/01	04:31:39	2937.31	25.3	00000000
637	03/01	04:31:29	2937.29	25.3	00000000
636	03/01	04:31:19	2937.29	25.3	00000000
635	03/01	04:31:09	2937.29	25.3	00000000
634	03/01	04:30:59	2937.30	25.3	00000000
633	03/01	04:30:49	2937.30	25.3	00000000
632	03/01	04:30:39	2937.30	25.3	00000000
631	03/01	04:30:29	2937.30	25.3	00000000

5 Calibration Menu




Fig 5-1: Calibration Menu

Calibrations can only be performed once the instrument has been installed, configured, and the channel has been set up. You must also ensure that you have the correct access rights to access the calibration menu.

It is recommended to calibrate the sensor once a month for applications of less than 50ppb, or once every three months for applications greater than 50ppb. The temperature sensor is factory calibrated and can only be changed by a Hach Ultra representative.

5.1 Sensor Calibration

The sensor can be calibrated either automatically at pre-defined intervals, or manually on an ad hoc basis. There are two calibration modes available - zero or high-level adjustment. The zero calibration method is the best calibration method to guarantee the sensor specifications. However, for higher level concentrations (such as 1% oxygen which corresponds to about 400 ppb dissolved O₂) a high-level adjustment can be performed.

By default, the mode is set to zero calibration with auto-end (see [“Calibration Configuration” on page 42](#) for more details), but these parameters can be changed.

Hach Ultra recommends that the sensor be calibrated on an automatic basis at regular intervals.

Note:

For zero calibrations, ensure a bottle of pure nitrogen gas is attached to the flow chamber as described in [“Calibration Gas” on page 23](#) and with the specifications defined in that same chapter. If a 34 liter bottle is used, and calibrations are automated on a monthly basis, you should only have to change this bottle once every three years.

5.1.1 Initial Sensor Calibration

After the instrument and sensor have been installed and configured, an initial calibration of the sensor must be performed. Before starting the calibration, wait at least 10 minutes with sample flowing through the system to ensure temperature equilibrium.

Select the **Configuration** option from the main sensor calibration menu to check the calibration parameters.

Ensure the parameters are set up to their default values as illustrated left:

- ☒ Auto-calibration: Off by default.
- ☒ Manual-calibration Auto-End: On by default.
- ☒ Hold during calibration or verification: On by default.
- ☒ Zero calibration bottle: On by default.
- ☐ New bottle: 34 liters by default. If using a different size bottle then update this parameter to reflect the size of the bottle and press **Apply**.

Exit from the configuration screen by pressing on **OK**. Then select **Calibration** from the main sensor calibration menu and perform a manual zero calibration as described in [“Zero Calibration” on page 44](#).

After a successful calibration, return to the configuration option (illustrated above) and enable auto-calibration. Select the **Auto-calibration Configure** option and set the number of days between calibration to 30 for applications less than 50ppb, or 90 for applications greater than 50ppb (see [“Configure Automatic Calibration” on page 43](#) for details). This will ensure an automatic calibration cycle.

Note:

There is no need to disable the manual calibration auto-end feature.

5.1.2 Automatic Calibration

If automatic calibration is the preferred option, ensure that this has been set up and that the parameters are correct. See [“Calibration Configuration” on page 42](#) for setting the calibration parameters.

When the calibration starts, the sample flow into the flow chamber is cut off automatically by the solenoid valve. Gas from the attached nitrogen gas bottle then flows through the flow chamber until measurements match the criteria set in **Stop parameters** or the time-out period of 10 minutes has elapsed.

Once the automatic calibration process is invoked, the message “Auto cal.” will flash alternately with the measurement on the numeric view screen for the duration of the calibration.

When the stability criteria is reached, the calibration process stops automatically and the calibration parameters are updated. Normal sample measurement then resumes.

If the stability criteria is not reached within a 10 minute period, the sensor cannot be calibrated and the process is aborted. After the delay defined in **Stop parameters**, a second calibration is then attempted. If this second calibration also fails, then an Auto. Cal error event is activated. Normal sample measurement then resumes but the calibration parameters unchanged.

Note:

If a calibration is unsuccessful, no calibration report will be created. The report is only created with a successful calibration.

5.1.3 Manual Calibration

Manual calibrations can be made at any time, even if the auto-calibration parameter is enabled. See [“Calibration Configuration” on page 42](#) for setting the calibration parameters, and [“Zero Calibration” on page 44](#) or [“High-Level Adjustment” on page 45](#) for details of the different calibration methods.

5.2 Calibration Configuration

This option can be invoked directly from the main calibration menu by selecting the **Configuration** option, or by pressing the **Modify** button in either the zero or high level calibration screens. The process sets all the parameters used for sensor calibration.

- ☒ Auto-calibration: Off by default. If enabled, press on **Configure** to set the auto calibration parameters (see [“Configure Automatic Calibration” on page 43](#)).
- ☒ Manual-calibration Auto-End: On by default. When enabled, a manual calibration will complete automatically when the parameters defined in **Stop parameters** are reached. Press on **Configure** to set the manual calibration parameters (see [“Configure Manual Calibration” on page 43](#) for details). If the calibration fails, the previous calibration parameters remain unchanged and a warning message displayed.
- ☒ Hold during calibration or verification: On by default. This keeps the last measured value and stops updating the outputs during the calibration or verification process. This avoids sending invalid information to any connected device. At the end of a calibration, this hold remains for a further 10 minutes to allow the system to stabilize.
- ☒ Zero calibration bottle: On by default. This tracks the usage of gas from the gas bottle used in the zero calibration. The remaining volume is displayed as a value and usage bar. When 10% or less of the total volume remains, a warning alarm event is triggered and the bottle should be replaced. When replacing the bottle, use this option to enter the volume (in liters) of the new bottle and press **Apply** to update.

If the **Stop parameters** button is pressed on the main configuration screen, you can view or change the existing values, or restore the default values.

It is highly recommended to leave these parameters at their default values and not change them.

These values apply to automatic calibrations and to manual calibrations with the **Auto-End** parameter set.

- ☐ Start period: is the minimum time period that must elapse before measurements are considered valid
- ☐ Number of points: is the minimum number of measurements that must be taken
- ☐ Stop criteria: is the maximum allowable signal standard deviation value to ensure an accurate calibration.
- ☐ Repeat autocal if failure: defines the time period that elapses before a second calibration attempt is made. A calibration failure event only occurs after the second failure.

5.2.1 Configure Automatic Calibration

This option sets the parameters for the sensor to be zero calibrated at a regular interval. The sensor should be installed in the specially designed flow chamber (see “[Sensor Installation](#)” on page 21) with a gas bottle of pure nitrogen attached.

The calibration mode is set to zero calibration and cannot be changed.

Details of the next calibration date are displayed. If the next calibration date is overdue, the word **Missed** is displayed.

- Enter the number of days between calibrations.

5.2.2 Configure Manual Calibration

This option sets the parameters required for manual sensor calibration.

- ▼ Calibration mode: 2 types available:

- Zero calibration
- High level calibration

If zero calibration is selected, no other parameters are required to be set. However, the following parameters must be set if high level calibration has been selected.

- ▼ Calibration sample: Set to **in line sample, gas bottle or factory parameters**. If factory parameters is selected, the Ksv value is displayed (as illustrated left) but can be changed.

Note:

The Ksv value should only need to be changed when replacing the sensor spot. The Ksv value of the new spot can be found on the 33021 kit box.


These additional parameters are required if in line sample or gas bottle has been selected as the calibration sample.

- ▼ Medium: This is automatically set to **liquid** if in line sample has been selected as the calibration sample, or **gas** if gas bottle has been selected.
- ▼ Gas unit type: Either **partial** or **dissolved** are available for an in line sample. If gas bottle was selected this is set to **fraction**.
- ▼ Gas unit: The list of available units depends on unit type selected above.
- ▼ Liquid: This defaults to **water**.

- Reference value: Enter the reference value for calibration

Press **OK** to return to the main calibration screen.

5.2.3 Zero Calibration



Start calibration

Configuration
Cal. mode: **Zero calibration** Modify


State
Sensor: **OK**

Measured values
Temp.: **24.8** °C
Fluor. phase: **26.579** °

Start Exit

With this method, the sensor should be exposed to pure N₂ gas using the specially designed flow chamber. Provided the sensor is attached to the flow chamber, this calibration method can also be automated (see [“Configure Automatic Calibration” on page 43](#)).

Press **Start** to start the calibration.



Under calibration, Cal. Time: 01:04

Results
Zero calibration: **37.01** % last calibration
Signal within range: **NO**
Stability reached: **NO**

State
Sensor: **Cal.**

Measured values
Temp.: **24.9** °C
Fluor. phase: **26.660** °
Pp O2: **196.23** mbar
Std deviation: **0.374** mbar

Finish Hide Cancel


A screen is displayed showing the measured values and length of time the sensor has been under calibration. These values are continually refreshed.

The value **% last calibration** displayed in the top box is an informational message showing the difference between the current and previous sensor calibrations.

The **Signal within range** and **Stability reached** boxes in the top right corner indicate whether the calibration is within acceptable limits. When both boxes indicate **YES**, press **Finish** to accept the new calibration. A confirmation screen then asks to accept and store the new parameters.

If one or both boxes show **NO**, you can still perform a calibration but it is not recommended, and the calibration should be aborted by pressing the **Cancel** button.

In the case of a calibration failure, attempt a second calibration after about 5 minutes. If the second attempt also fails, then refer to your Hach Ultra representative for advice.




Warning

Auto-end calibration
Store new calibration parameters

Yes No

Note:

*If the Auto-End parameter is set (see [“Calibration Configuration” on page 42](#)), then the calibration will be deemed successful when the parameters defined in **Stop parameters** are met. You will then be asked to confirm the calibration.*



Warning

The maximum time for a proper calibration has elapsed. It is advised to cancel this calibration procedure and start again.

OK

If you have not accepted or cancelled the calibration after an elapsed time of 10 minutes then the process will time-out, and the warning message illustrated left will be displayed.

5.2.4 High-Level Adjustment

This calibration exposes the sensor to a gas or a liquid sample with a known gas concentration. You also have the option to reset the sensor's calibration parameters to factory settings (from drop-down list for **Cal. sample**).

The screen example illustrated is for calibrating using a liquid sample. The screen for calibration using a gas bottle differs only slightly.

Press **Start** to start the calibration. The process is then the same as for the zero calibration described previously.

5.3 Sensor Verification

Similar to the calibration procedure, but for verification of the actual calibration values. The results of the measurements made during the verification are not stored and the actual calibration data is not modified.

5.4 Barometric Pressure Calibration

Note:

The barometric sensor has been factory calibrated but should be periodically verified with a precision certified barometer. This is only necessary if measuring in gas phase with fraction units (% , ppm).


The upper box shows the barometric pressure as measured by the instrument.

Using a precision certified barometer, measure barometric pressure in the location where the measuring instrument is used. Compare the values, if values are the same press **cancel**, otherwise enter the new barometric value in the lower box and **validate** the new setting.

Once the calibration is completed a calibration report is generated.

5.5 Calibration Reports

Once a calibration is completed (for a gas or pressure sensor) successfully, the calibration report is updated with the new details. The calibration report contains data for the last 10 calibrations. The example illustrated below is for a gas sensor calibration. For full details on the data displayed for all calibration reports, refer to “[Gas Sensor Calibration Report Example](#)” and “[Barometric Sensor Calibration Report Example](#)” on page 62.



Each calibration record will contain parameters useful for traceability. For instance, it will contain:

- the date and time
- the calibration mode (zero or high level)
- the calibration type (manual or automatic)
- the operator name and ID
- all the measurements which influence the calibration

6 Inputs/Outputs Menu




Fig 6-1: Inputs/Outputs Menu

6.1 Configure Snooze

In the event of an alarm, the “snooze” button stops the instrument buzzer and returns all the relays in the instrument to their normal state during a “snooze time”.

- Enter the snooze time in seconds and press OK.

6.2 View Inputs/Outputs

View Inputs/Outputs			
	Out 1	Out 2	Out 3
Relay	On	On	On
Analog output	3.99 mA		

Cancel

This view option displays the state of the 3 alarm relays (on or off), and the analog output current (or voltage, depending on the instrument version) value for each.

6.3 Relays

There are three measurement alarm relays and one system alarm relay. These relays are configurable as either standard or custom events through the instrument menu.

Notes regarding the relays:

- An alarm relay can be activated or deactivated
- When the alarm is OFF, it is activated,
- When the alarm is ON, it is deactivated

All the relays are activated as soon as the instrument is ON (but alarms are OFF). When the instrument is OFF, the relays are deactivated, thus in this state, all alarms are ON. The logic "Relay deactivated = Alarm ON" has been chosen for this safety reason.

When the main board does not communicate with the measurement board for more than 30 seconds, the measurement board switches all the alarm relays and the analog output to the alarm state.

6.3.1 Relay Configuration

Relays configuration	
Relay 1	Standard events: Custom events Configure
Relay 2	Standard events: High High Configure
Relay 3	Standard events: None Configure

OK Cancel

The three measurement alarm relays can be triggered by several standard events, or a combination of events (custom). The relays output can be used to turn on a beacon, horn or PLC (see ["Connections to Electronic Boards" on page 19](#))

Note:
Relays can be set to Normally Open [NO] or Normally Closed [NC] by changing the jumper positions on the measurement board (see ["Measurement Alarm Relays" on page 20](#)).

Relay 1 - Standard events	
Low Low	▲ ▼
Low	
High	
High High	
Critical events	
Custom events	
None	

OK Cancel

- ▼ Select a standard event in the rolling list
- ☞ If "Custom event" has been selected, it has to be configured by touching the **configure** button

Custom events configuration

Custom event mask = High High

OR Low Low

OR None

OR None

OR None

OR None

OR None

OK Cancel

▼ Click on the text box to open the selection menu (rolling menu). Select the events that must trigger the relay, and press OK.

The example shown here will trigger the relays whenever the value is above the High High or under the Low Low preset values.

Custom event mask =

None

Measurement started

Calibration

Hold

Low Low

Low

High

High High

Calibration required

Service required

Continuous Purge On

Burner backup failure

OK Cancel

Proceed in the same manner for other event that should trigger the relay

6.3.2 Test Channel Relays

Test channel relays

Relay 1 On

Relay 2 Off

Relay 3 Not under test

Cancel

The three measurement alarm relays can be manually activated for testing purposes:

▼ Select Relay **On**, **Off** or **Not under test**.

“Not under test” means the relay is in operating mode, and it will be triggered normally.

Note:

A relay set to NO will close when activated (**On**), but a relay set to NC will open. See “Measurement Alarm Relays” on page 20

6.3.3 Test System Relay

Test system relay

System relay Not under test

Cancel

Similarly, the system alarm relay can be manually activated for testing purpose.

▼ Select Relay **On**, **Off** or **Not under test**.

See “Analog and Digital Outputs” on page 99

6.4 Analog Output

There are three analog outputs available. The outputs are configurable in terms of function, content, and behavior through the instrument menus. Analog outputs are used to output a voltage or a current which is a function (e.g a linear characteristic) of a measurement: $AOut = f(M)$. The analog outputs can be typically connected to a PLC. Knowing the function (f), the PLC can compute the value of the measurement.

Two types of instrument hardware are available:

- measurement board with current output ($I = 0-20$ mA or $4-20$ mA).
- measurement board with voltage output ($U = 0-5$ V).




Fig 6-2: Analog Outputs Menu

6.4.1 Instrument Configuration

- ▼ Select analog output range of current:
4-20 mA or 0-20 mA
- ▼ The 4-20 mA range (recommended) allows for an extended event indication mode that can be selected and configured (default = standard mode)

Note:

Features of instrument with a voltage analog output are similar to the 0-20 mA features.

For some events (sensor out, purge failure, etc.) the actual measurement is not significant, but the PLC needs to know how the analog output behaves in these cases. Two "Event indication modes" are available:

- Standard mode (default)
- Extended mode

Standard Event Indication

Analog Output	Event output range			Event
	0-20 mA	4-20 mA	0/5 V	
Gas concentration	20 mA	20 mA	5 V	- Channel out - Sensor out - Thermal cut-off - Interfering gas error
Temperature	20 mA	20 mA	5 V	- Channel out - Sensor out

Extended Event Indication

The "Extended event indication" mode is only available when the 4-20 mA output is selected. In this mode, the range between 0 mA and 4 mA is used to indicate selected events. The events are defined using the channel configuration option (see ["Channel Configuration" on page 52](#)).

Note:

This mode is not available on voltage output versions of the instrument.

6.4.2 Channel Configuration

Set the type of measurement that will be transmitted through each output channel, and the output characteristics.

- ▼ Meas. type: Select between the type of measurements available in the rolling list.
- ▼ Characteristics: Select either Mono-linear, Tri-linear or None (see [“Analog Output Characteristics” on page 56](#))

- ⇒ Limits: Press the configure button to adjust the analog output set points for each output. Enter values in the appropriate text boxes. In Mono linear mode, only the ML and MH values can be adjusted. Tri linear mode allows all limits to be adjusted, and the None mode denies access to this screen.

- ⇒ The user may define a maximum of 12 customized events for each analog output and change the order of priority of all events.

Note:

This only applies to Tri linear and Mono linear outputs. It is not available if the output characteristic is set to None.

Configure the events that should be signaled at the corresponding current shown in the right column.

- Only one event signal at a time can be sent via the current output. As there is a possibility to have several events at the same time, an order of priority must be set. This order has been set by default, but it can be modified to suit particular needs and conditions. Touch the priority number in the left column and edit it.
- The shaded events in the list have preset outputs and only the priority can be changed. The other events can be customized by the user. Touch a white text box to call up the rolling list. Select an event from this list and press OK. Then adjust the priority as required.

Note:

When an event occurs, measurement information is superseded by the event information on the output.

The following table lists the default configuration. The first two events on the list are pre-set and only the priority can be changed.

Table 6-1: Extended Event Table

Priority	Event	I [mA]
0	Sensor out	0.25
1	Interfering gas error	0.50
2	Custom Event 1	0.75
3	Custom Event 2	1.00
4	Custom Event 3	1.25
5	Custom Event 4	1.50
6	Custom Event 5	1.75
7	Custom Event 6	2.00
8	Custom Event 7	2.25
9	Custom Event 8	2.50
10	Custom Event 9	2.75
11	Custom Event 10	3.00
12	Custom Event 11	3.25
13	Custom Event 12	3.50
14	Custom Event 13	3.75

6.4.3 Calibration

The calibration of the analog output is aimed at aligning the internally calculated current to the real current output. This was performed at factory, but could become necessary again because of electronic tolerances. A precision amperometer (or voltmeter for the voltage versions) connected at the corresponding analog output connection point is required. See “Measurement Board” on page 20.

Analog outputs calibration

Help

Step 1 : Please select "Output Nb", choose the output to calibrate and press "Start".

Output Nb

1

Point 1

0

mA

Point 2

20

mA

Start

Cancel

Select the analog output number to calibrate and press the start button.

Analog outputs calibration

Help

Step 2 : Please select "Point 1", enter the output value measured and press "Continue".

Output Nb

1

Point 1

0

mA

Point 2

20

mA

Continue

Cancel

Measure with the amperometer the current value for point 1. It should be below 4 mA
Edit point 1 and enter the same value as read on the amperometer, then press the “continue” button.

Analog outputs calibration

Help

Step 3 : Please select "Point 2", enter the output value measured and press "Continue".

Output Nb

1

Point 1

0

mA

Point 2

20

mA

Continue

Cancel

Measure with the amperometer the current value for point 2. It should be above 20 mA.
Edit point 2 and enter the same value as read on the amperometer, before pressing the “continue” button.

Analog outputs calibration

Help

Step 4 : Calibration is done. Press "Restart" to calibrate another output or "Cancel" to exit.

Output Nb

1

Point 1

0

mA

Point 2

20


mA

Restart

Cancel

Calibration of the selected analog output channel is completed.

6.4.4 Direct Test



Test analog outputs

Out 1 Not under test

Out 2 Not under test

Out 3 Not under test


Cancel

Test to check the calibration of the analog outputs. A precision amperometer connected at the analog output connection point is required.

- ▼ Select a value (4, 12, 20 mA available) for each channel and compare this value (± 0.02 mA) with what the amperometer shows.

A calibration is required if the value on the amperometer differs from the current selected ± 0.02 mA).

6.4.5 Characteristics Test



Test analog outputs characteristic

Out 1 8339.2 ppb

Out 2 24.6 °C

Out 3 0.976 bar

Cancel

This is a test for the correct operation of the peripherals connected to each analog output, by verifying that the PLC computes the correct value.

The analog output will send the current corresponding to the value entered in the text boxes.

- Type in a test value for each analog output, and check for the related action on the peripheral.

6.5 Analog Output Characteristics

6.5.1 “Linear” Analog Output

The "Linear" output is the default setting for the analog outputs. It is illustrated in [Fig 6-3](#) below (4-20 mA output is shown, 0-20 mA or 0-5 V settings are similar). The goal of this setting is to use all the points available on the slope from 4 mA to 20 mA to show the range of measurements that are usual in the measured process. Setting the output this way allows for the highest signal resolution for the actual conditions.

The downside is that any measures below the set range will have the same analog signal locked at 4 mA. Similarly, any measure over the set range will have the same analog signal locked at 20 mA. Settings must be made in balancing these aspects.




Fig 6-3: “Linear” Characteristics Diagram

Settings

For the output, set ML and MH in the current measuring unit (e.g. °C for a temperature output). When a compound unit is selected the smallest unit will be used (e.g. ppb for a "ppm-ppb" compound unit).

These points should be set keeping in balance the following conditions (see figure):

- The smaller is Range 1, the better is the analog signal resolution within the expected range of measure.
- In Range 0 the analog output only shows that measurement is below the ML value. Similarly in Range 2 the analog output only shows that measurement is over the MH value.

The formula to compute the measurement knowing the current I (or voltage U) and the resolution R is given in the following table:

Output type Linear:	Range	Measurement M	Resolution R
4-20 mA	$20 > I > 4$	$M = ML + (MH - ML) \cdot (I - 4) / 16$	$R = (MH - ML) / 808$
0-20 mA	$20 > I > 0$	$M = ML + (MH - ML) \cdot I / 20$	$R = (MH - ML) / 1010$
0 - 5 V	$5 > U > 0$	$M = ML + (MH - ML) \cdot U / 5$	$R = (MH - ML) / 1010$

6.5.2 “Tri-linear” Analog Output

The “Tri-linear” output brings benefits over the “Linear output” discussed before. It is illustrated in Fig 6-4 below (4-20 mA output is shown, 0-20 mA or 0-5 V settings are similar).

Compared to the “Linear” mode, the expected range of measure is Range 2. A Range 1 and 3 are available to show the measures falling out of this Range 2, but normally at a lower resolution. Expected measurements for the measured process are supposed to be in Range 2 most of the time, and in Range 1 or 3 occasionally (problems, calibration, line stop, etc.).




Fig 6-4: “Tri-linear” Characteristics Diagram (4-20 mA shown)

The benefits are:

- The PLC can compute the measurement over a large range (1, 2 and 3).
- The PLC can compute a higher resolution signal for the expected measuring range (Range 2: $MH > M > ML$).
- Carefully selecting the set points allows for an individual resolution for each range, so a different resolution can be applied to Range 1, 2 and 3, allowing to tailor the analog output to the actual conditions.

As before, the downside is that any measure below or over the Range 1, 2 and 3 will have the same signal locked at 4 mA and 20 mA respectively, but Range 1, 2 and 3 should cover a larger range than in the “Linear” mode. Settings must be made in balancing these aspects.

Settings

For each output, set MLL, ML, MH, and MHH in the current measuring unit (e.g. °C for a temperature output). When a compound unit is selected, the smallest unit will be used (e.g. ppb for a “ppm-ppb” compound unit). Also set AOL (Analog Output Low) and AOH (High) in mA (or Volts).

These points should be set keeping in balance the following conditions (see [Fig 6-4 on page 57](#)):

- The smaller is Range 2, the better is the analog signal resolution within the expected range of measure.
- Size of Range 1 and 3 should be set to deliver an adequate level of resolution for the measures falling out of the expected range of measure.
- In Range 0 the analog outputs only shows that measurement is below the MLL value. Similarly in Range 4 the analog output only shows that measurement is over the MHH value.

The formula to compute the measurement knowing the current or the voltage and the resolution R is given in the following table:

Output type Tri-linear:	Range	Measurement M	Resolution R
4-20 mA	1: $AOL \geq I > 4$	$M = MLL + (ML - MLL) \cdot (I - 4) / (AOL - 4)$	$R = (ML - MLL) \cdot 20 / ((AOL - 4) \cdot 1010)$
	2: $AOH \geq I > AOL$	$M = ML + (MH - ML) \cdot (I - AOL) / (AOH - AOL)$	$R = (MH - ML) \cdot 20 / ((AOH - AOL) \cdot 1010)$
	3: $20 > I > AOH$	$M = MH + (MHH - MH) \cdot (I - AOH) / (20 - AOH)$	$R = (MHH - MH) \cdot 20 / ((20 - AOH) \cdot 1010)$
0-20 mA	1: $AOL \geq I > 0$	$M = MLL + (ML - MLL) \cdot I / AOL$	$R = (ML - MLL) \cdot 20 / (AOL \cdot 1010)$
	2: $AOH \geq I > AOL$	$M = ML + (MH - ML) \cdot (I - AOL) / (AOH - AOL)$	$R = (MH - ML) \cdot 20 / ((AOH - AOL) \cdot 1010)$
	3: $20 > I > AOH$	$M = MH + (MHH - MH) \cdot (I - AOH) / (20 - AOH)$	$R = (MHH - MH) \cdot 20 / ((20 - AOH) \cdot 1010)$
0-5 V	1: $AOL \geq U > 0$	$M = MLL + (ML - MLL) \cdot U / AOL$	$R = (ML - MLL) \cdot 5 / (AOL \cdot 1010)$
	2: $AOH \geq U > AOL$	$M = ML + (MH - ML) \cdot (U - AOL) / (AOH - AOL)$	$R = (MH - ML) \cdot 5 / ((AOH - AOL) \cdot 1010)$
	3: $5 > U > AOH$	$M = MH + (MHH - MH) \cdot (U - AOH) / (5 - AOH)$	$R = (MHH - MH) \cdot 5 / ((5 - AOH) \cdot 1010)$

6.5.3 “None” Analog Output

This is the default value.

Setting the analog output to “None” means that the output value will always be zero and importantly ensures that no current is emitted, so reducing power consumption as well as reducing heat within the instrument.

7 Communication Menu






Fig 7-1: Communication Menu



The external RS-485 port of the main board is directly connected to a RS-485 bus (single twisted pair). Optionally it can be connected to a fieldbus module (gateway). In this case, the fieldbus module has a RS-485 port connected to the RS-485 bus.

The RS 485 menu allows to select between RS485 simple or Profibus DP communication protocol, depending on application.

- ▼ Click on the text box to select either the RS-485 simple or the PROFIBUS-DP communication protocol.



7.1 RS-485 Simple Mode Configuration

This protocol allows the instrument to output data to an external device (PLC, SCADA, PC, etc.). The communication is unidirectional. The data are output on the RS-485 link as simple ASCII text. If for instance you use a PC, the data can be easily visualized and saved in a file using the "Hyperterminal" software.

To use this communications mode, on the instrument:

- Select the menu "Communication/RS-485" and choose the protocol "Simple" (default configuration).
- Select the menu "Communication/RS-485 Simple/Configuration".

- "Baud rate", "Parity", "No of stop bits", "Byte size" Standard parameters of the RS-485 link.
- "Enable" The measurements can be sent continuously (approximately every 2 sec.). This field allows enabling or disabling this feature.
- "Mode" This is the format of the measurements sent continuously (see ["Cyclic Measurements" on page 61](#) of this document). In "Expert" mode, more data are sent. These additional data can be useful for diagnostic purpose.

Note:

In case of problem verify first that jumper J3 is not installed on the mother board (default configuration).

Send Data

This dialog box is used to send text files to an external device. The possible files are the following:

- Calibration reports
- User actions log file
- Instrument configuration
- Measurements stored in the instrument memory.

The button "Stop Cyclic meas." allows to stop and to restart the cyclic transmission of measurements. It is advised to stop the cyclic transmission in order not to mix cyclic measurements and data of the file being transmitted. This button has the same effect as the "Enable" checkbox of the "Communication/RS-485 Simple/Configuration" window.

After stopping the cyclic measurements, select the "Calibration Reports", "User Actions", "Configuration", "Measurements" button to send the corresponding file, or the "All files" button to send all these files in one shot.

Once the button is pressed, the file is sent immediately. The field "Current file status" shows "Sending" alongside the file transmission progress bar. On completion this changes to "Sent".

7.1.1 Data Available

All individual data are separated by at least one tabulation character (ASCII code=0x09).

For the cyclic measurements, the data format is detailed. For the files, only one example for each file is given to explain the data format.

Cyclic Measurements

- 1) If the option "Mode = standard" is chosen, the following message is sent:

CHn\t	Gas\t	Gas Unit\t	Temperature\t	Temperature Unit\t	Barometric Pressure\t	Barometric Pressure Unit\t	Event\t\r\n
-------	-------	------------	---------------	--------------------	-----------------------	----------------------------	-------------

with:

\tthe ASCII tab character: code=0x09
 \rthe ASCII Carriage Return character: code=0x0D
 \nthe ASCII Line Feed character: code=0x0A
 CHnthe 2 ASCII characters "CH" + the channel no.
 Gasthe gas concentration.
 Gas Unitthe gas unit.
 Temperaturethe temperature.
 Temperature Unitthe temperature unit.
 Barometric Pressurethe barometric pressure.
 Barometric Pressure Unitthe barometric pressure unit.
 Eventthe event bit mask in hexadecimal format.

The values are not described here (See "List of Events and Alarms" on page 94).

- Example of one measurement:

CH1 697.176 ppb 20.1 °C 0.982 bar C00

- 2) If the option "Mode = expert" is chosen, the following message is sent:

CHn\t	Gas\t	Gas Unit\t	Temperature\t	Temperature Unit\t	BarometricPressure\t	Barometric Pressure Unit\t								
<table><tr><td>Event\t</td><td>Phase Shift\t</td><td>°\t</td><td>Partial Pressure\t</td><td>bar\t</td><td>Reference Phase\t</td><td>°\t</td></tr></table>							Event\t	Phase Shift\t	°\t	Partial Pressure\t	bar\t	Reference Phase\t	°\t	
Event\t	Phase Shift\t	°\t	Partial Pressure\t	bar\t	Reference Phase\t	°\t								
<table><tr><td>Fluorescent Phase\t</td><td>°\t</td><td>Reference Ampt\t</td><td>V\t</td><td>Fluorescent Ampt\t</td><td>V\t</td><td>Time\t</td><td>Index\r\n</td></tr></table>							Fluorescent Phase\t	°\t	Reference Ampt\t	V\t	Fluorescent Ampt\t	V\t	Time\t	Index\r\n
Fluorescent Phase\t	°\t	Reference Ampt\t	V\t	Fluorescent Ampt\t	V\t	Time\t	Index\r\n							

with:

Phase shiftThe fluorescence phase shift in [°].
 Partial pressureThe partial pressure in [bar].
 TimeThe time of the measurement. Format "hh:mm:ss."
 IndexThis is the index of the last measurement.

This number starts at 0 at power up of the program. The following is an example of one measurement:

CH1 697.173 ppb 20.1 °C 0.982 bar C00 26.045 ° 0.69700 bar
 -21.409 ° -64.991 ° 2.349 V 2.493 V 12:59:42 5923

Gas Sensor Calibration Report Example

Calibration report nb 1
 Mode Manual high level calibration
 Date (yy.mm.dd - hh:mm) 05.02.17 - 18:40
 Operator jp
 Operator ID 3
 Calibration sample. In line sample
 Medium Liquid
 Gas unit ppb
 Liquid Water
 Reference value 1.500000
 Calibration coefficient Phi0 . . . 25.974°C
 Calibration coefficient Tcal . . . 24.41°
 Calibration coefficient Ksv . . . -0.1312 mbar-1
 Standard deviation 0.003 mbar
 Fluorescent amplitude 0.834 V
 Temperature 20.1 °C
 Calibration duration 3 mn

Barometric Sensor Calibration Report Example

Calibration report nb 1
 Date (yy.mm.dd - hh:mm) 05.02.16 - 20:38
 Operator jp
 Operator ID 3
 Previous barometric pressure . 0.956 bar
 New Barometric pressure 0.976 bar
 Calibration offset 3.73 [kPa]

User Action Log File Example

The "User action log file" below contains 3 user actions.

<i>Nr</i>	<i>mm/dd</i>	<i>hh:mm:ss</i>	<i>User ID</i>	<i>User Name</i>	<i>Action ID</i>	<i>Description</i>
1	1/21	15:13:44	1007	Armstrong	139	Change Time/Date
0	1/21	15:13:27	1007	Armstrong	501	Calibration parameters
2	1/21	15:12:15	1007	Armstrong	132	Identification

Configuration Report Example

INSTRUMENT CONFIGURATION

Measurement mode Continuous mode
 Pressure unit bar
 Temperature unit °C
 Storage mode Rolling buffer
 Storage RAM time 10 [s]
 Storage FLASH time 3600 [s]

 Membrane Power OT
 Medium Liquid
 Gas unit ppm->ppb
 Liquid Water
 Resolution displayed 1
 Thermal cut off Disabled 65.0 [°C]
 Alarm Low Low Enabled 100.000000 [ppb]
 Alarm Low Enabled 200.000000 [ppb]
 Alarm High Enabled 9000.000000 [ppb]
 Alarm High High Enabled 10000.000000 [ppb]
 Alarm Hysteresis 5 [%]
 Alarm Delay 15 [s]
 Filter State Enabled
 Filter Type Median
 Filter Depth 5
 Filter Central depth 1

Measurement File Example

6 measurements are described below:

<i>Nr</i>	<i>mm/dd</i>	<i>hh:mm:ss</i>	<i>Gas</i> [ppb]	<i>Temp</i> [°C]	<i>Mask</i>	<i>Fluor. phi</i> [°]	<i>Barom</i> [bar]	<i>Ext P.</i> [bar]	<i>Index</i>
0	2/17	21:15:37	75.051	20.1	400	26.039	1.005	1.977	2271
1	2/17	21:15:27	75.043	20.1	400	26.045	1.005	1.976	2266
2	2/17	21:15:17	75.047	20.1	400	26.052	1.005	1.976	2261
3	2/17	21:14:57	75.044	20.1	400	26.041	1.005	1.976	2256
4	2/17	21:14:47	75.047	20.1	400	26.038	1.005	1.977	2251
5	2/17	21:14:37	75.050	20.1	400	26.054	1.005	1.976	2246

7.1.2 Example of Use

In this example we use:

- One PC with a RS232 port.
- One "RS-485<->RS232 converter"

Procedure:

- 1) Connect both RS-485 wires of the instrument to the "RS-485<->RS232 converter".
- 2) Connect the "RS-485<->RS232 converter" to the PC RS232 port using a standard cable (RS232 DB9 straight cable).

On the PC:


- 1) Run "Hyperterminal" on the PC.
- 2) Configure the PC COM port used (e.g. COM2). Menu "File/Properties/Configure".
- 3) Configure the parameters "Baud rate", "Parity", "Nb of stop bits", "Byte size" (Menu "File/Properties/Configure"). Use the same parameters for the instrument and the PC.
- 4) Configure the "Font = Courier 10" (Menu "View/Font").
- 5) Connect "Hyperterminal" (Menu "Call/Call").
- 6) Save the data received in the file of your choice (Menu "Transfer/Capture Text/Start").

On the instrument:

- 1) Use the menu "Communication/RS-485 Simple/Send files" and the button "All files".

When the transfer is finished, close the file with "Hyperterminal" (Menu "Transfer/Capture Text/Stop"). Now, all the reports are saved in a text file on your PC.

7.2 PROFIBUS-DP Communication (optional)



7.2.1 Installation

On the Orbisphere CD, there is an "Orbi2079.gsd" and an "Orbi2079.bmp" file available in the "Profibus DP" folder to help configure the PROFIBUS-DP. The GSD file contains the following elements:

- A module to decode the barometric pressure value and unit
- A module to convert the channel measurement data such as gas concentration, gas unit, temperature, temperature unit and the events.




WARNING


Installation should be performed exclusively by personnel specialized and authorized to work on electrical installations, in accordance with relevant local regulations. Disconnect the power supply of the instrument before carrying out any work inside the instrument.

CAUTION:

Proper ESD (electrostatic discharge) protocols must be followed to prevent damage to the product. All fittings must be properly seated and tightened to prevent any water and dust ingress.

- 1) Install the PROFIBUS-DP module and the jumper J3 on the main board (location highlighted in the illustration below).





- 2) Select the menu "Configuration/RS-485" and choose "PROFIBUS-DP" as the protocol.
- 3) Select the menu "Configuration/PROFIBUS-DP", choose the slave address and restart the instrument.

7.2.2 Input/Output Data

The main board:

- Writes the latest measurement data to the Profibus Input Buffer.
- Checks if a command written by the Profibus Master must be executed (Profibus Output Buffer). If a command is to be executed, the instrument executes it and writes the result (status, data, etc.) in the Profibus Input Buffer.

All numbers are coded in "Big Endian" format, and float values are coded according to IEEE Standards. The field types "Byte" and "Double Word" are unsigned.

7.2.2.1 Measurements

Measurements are formatted in the Profibus Input Buffer as follows:

Name	Type	Size	Offset
Barometric pressure	Input float	32 bits	0
Barometric pressure unit	Input byte	8 bits	4
Channel 1 gas concentration	Input float	32 bits	5
Channel 1 gas unit	Input byte	8 bits	9
Channel 1 temperature	Input float	32 bits	10
Channel 1 temperature unit	Input byte	8 bits	14
Channel 1 external pressure	Input float	32 bits	15
Channel 1 external pressure unit	Input byte	8 bits	19
Channel 1 events	Input double word	32 bits	20
Channel 1 measurement index	Input double word	32 bits	24

The gas, temperature and barometric pressure unit values are coded as defined in the following tables:

Gas Unit	Value
bar	0
mbar	1
Pa	2
kPa	3
hPa	4
psia	5
atm.	6
mbar->bar	9
Pa->kPa	10
%Vbar	12
ppm Vbar	13
%Vext	14
ppm Vext	15
ppm Vbar->%Vbar	16
ppm Vext->%Vext	17
ppm	18
ppb	19
g/l	20
mg/l	21
µg/l	22
%O ₂	23
%Air	24
g/kg	25
V/V	26
%W	27
cc/kg	28
ml/l	29

Temperature Unit	Value
K	0
°C	1
°F	2

Barometric Pressure Unit	Value
bar	0
mbar	1
psia	2
atm.	3
Pa	4
kPa	5
hPa	6

Note:

For the field "Event", please see the column "Bit mask value" in [Table 12-1, "List of Events," on page 94](#)

Note:

If the instrument stops sending measurement data to the module, then after 30 seconds the module sets the event mask to the value **PROFIBUS-DP value not updated** (0x80000000) bit mask.

7.2.2.2 Commands

The “Command Output Buffer” is formatted as follows:

Name	Type	Size	Offset
Output command toggle (OCT)	Output byte	8 bits	0
Output command ID (OCI)	Output byte	8 bits	1
Output command data byte 1 (OCD1)	Output byte	8 bits	2
Output command data byte 2 (OCD2)	Output byte	8 bits	3
Output command data byte 3 (OCD3)	Output byte	8 bits	4
Output command data byte 4 (OCD4)	Output byte	8 bits	5

The “Command Input Buffer” is located just after the measurement data and is formatted as follows:

Name	Type	Size	Offset
Input command toggle (ICT)	Input byte	8 bits	74
Input command status (ICS)	Input byte	8 bits	75
Input command data byte 1 (ICD1)	Input byte	8 bits	76
Input command data byte 2 (ICD2)	Input byte	8 bits	77
Input command data byte 3 (ICD3)	Input byte	8 bits	78
Input command data byte 4 (ICD4)	Input byte	8 bits	79

The following commands are available:

- Change product
- Activate sensor (valid for EC sensors only)

Change Product Command - Output

Name	Value	Comment
OCT	1-2	
OCI	1	
OCD1	0	Channel number: 0 = Channel 1
OCD2	0-99	Product number
OCD3	0-1	Erase measurement files: 0 = Never erase the measurement files. 1 = Erase measurement file if necessary (e.g. gas unit changes)
OCD4		Not used

Change Product Command - Input

Name	Value	Comment
ICT	1-2	
ICS	0-3	0 = OK 1 = Unknown command ID 2 = Invalid parameter (e.g. invalid channel no or product number) 3 = Execution failure
ICD1		Not used
ICD2		Not used
ICD3		Not used
ICD4		Not used

Activate Sensor Command - Output


Name	Value	Comment
OCT	1-2	
OCI	2	
OCD1	0	Channel number: 0 = Channel 1
OCD2	0-1	Sensor activation: 0 = Deactivate the EC sensor 1 = Activate the EC sensor
OCD3		Not used
OCD4		Not used

Activate Sensor Command - Input

Name	Value	Comment
ICT	1-2	
ICS	0-3	0 = OK 1 = Unknown command ID 2 = Invalid parameter (e.g. invalid channel no) 3 = Execution failure
ICD1		Not used
ICD2		Not used
ICD3		Not used
ICD4		Not used

7.3 USB-A Port (host)

This option allows the export or import of data from an external mass storage device. The device must first be connected to the instrument through the USB-A port.



Select one of the two import options (product list or access table) to import data from the storage device. This is useful for transferring these files to additional instruments without the need of having to re-enter the data individually on each instrument.

Note:

The imported data will override any current settings on the instrument.


Select the export option to export data from the instrument to the storage device. For information regarding the uploaded files, refer to [“Uploaded Files” on page 76](#).

For both import and export options, the progress bar is updated to give an indication of the progress of the selected option.


7.4 HTTP/TCP-IP

7.4.1 Overview

When activated this option downloads data from the instrument directly to a web page that can be accessed from a PC. To be able to use this option, the instrument must be connected to the network (specifically **Connector P3** - see details in [“Main Board Connections” on page 19](#)) and the network must have a DHCP server installed.



- ☒ Check the Enable server box to enable the web server communication link.
- ☐ Enter the Server name for the instrument. This is free format text and should typically be used to identify the instrument.
- ☒ Check the Enable security box if you require a password to be entered on the PC to access the web page.



If any of the details on the previous screen have been changed, a warning message will be displayed as illustrated left.


The changes must be confirmed, after which the instrument must be powered down and powered up again for the changes to take effect.

Note:

The IP Diagnostics button at the bottom of the screen is for use by experienced IT personnel only to help resolve any communications problems.

7.4.2 PC Interface


Once the server has been enabled and the interface information set up, access the information by launching an internet browser and typing “**http://**” followed by the server name that has been assigned to the instrument, in the address box as illustrated below:




If the enable security option has been checked on the instrument, you will be required to enter a username and password on your PC to gain access to the web page.

The username and password must be a valid username/password combination that has been set up on the instrument (see also “[User Management](#)” on page 79 on how to set up users on the instrument). Domain information is not required.

Once a valid username/password combination has been entered, the initial web page will be displayed giving a list of options:



Click on any of these options and the data will be displayed on the PC screen. The following shows an example of the screen when selecting the Current Measurement option:




7.5 Data File Transfer Through the USB-B Port (client)

The USB port allows you to copy data files from the instrument to a PC using the Microsoft ActiveSync® software. The files in the instrument are coded in a binary format, so they must be converted to a readable format on your PC to make them suitable for viewing. This is done automatically using the software supplied on the Orbisphere CD (see “PC Software Installation” below and “Upload Report Files” on page 75 for details).

Check that the instrument and PC are powered, then connect them with the USB cable that was supplied with the instrument. Follow the instructions below:

7.5.1 PC Software Installation

Insert the Orbisphere CD inside the PC drive. If the auto executable installation does not start, browse the CD with Windows Explorer and double click on the “setup.exe” file to start the installation. Follow the step by step instructions appearing on the screen.



Once the installation is complete, two icons are installed on the PC Desktop:



Orbisphere USB upload is used to upload and convert report files from the instrument to the PC. See [“Upload Report Files” on page 75](#).



Orbisphere Install is an installation software used by the Hach Ultra after sales technicians to upload new software versions. To avoid an accidental software modification, a key is required.

7.5.2 Microsoft ActiveSync® Configuration

The latest version of ActiveSync® can be downloaded and installed from:

www.microsoft.com/windowsmobile/downloads

Note:


A copy of the ActiveSync® software is also available on the Orbisphere CD. Inside the ActiveSync folder, double click the “MSASYNC.EXE” executable file to install on the PC.



Once successfully installed ActiveSync® starts automatically each time the Orbisphere instrument is connected to the PC.

CAUTION:

By default ActiveSync® proposes to set up a partnership with the instrument. This is not required, so make sure this is set to **NO** (as illustrated left) before continuing.



The ActiveSync® screen is then displayed and an icon will appear in the taskbar at the bottom of your screen.




When active the icon in the taskbar is colored green (as illustrated top left) and when inactive, the icon is still visible but greyed out (as illustrated bottom left).

7.5.3 Upload Report Files

Double click on the **Orbisphere USB upload** icon on the PC desktop (created during the process described previously in “PC Software Installation”) to start the upload and convert process.

When the main screen is displayed, click on the Wizard button  in the top left corner.


Step 1



Check that the USB connection from the instrument to PC has been made, and that the ActiveSync® software has been activated and the link recognized (the icon in the taskbar should be colored green).


Click on Next.

Step 2




Choose the directory where the files are to be stored. If the directory path does not exist it will be automatically created.

Click on Next.




A warning message appears to warn that all files currently in the directory (if any exist) will be deleted prior to upload.

Click on Yes to continue with the process or No to abort. If Yes is selected, a progress bar of the upload is displayed.



Should any of the files be missing (e.g. a calibration file will be missing if no calibration has been performed), a warning message is displayed, but no action is required. Click on OK.

Step 3



Once the upload is complete, the files are converted and stored in the folder defined in Step 2 above.

Click on Finish to terminate the process, or on either of the other two buttons to open the folder or view the text files.


Uploaded Files

There are a number of files that are uploaded to the PC during this process. However, only the text files (with a **.txt** file extension) are in a readable format on the PC. Most document editors (Word, Notepad, etc.) can be used to open these files, as well as spreadsheet and other reporting tools (e.g. Excel).

There are four reports available:

- Instrument Configuration
- Calibration Reports
- Measurements
- Product Lists
- User Actions

The reports show information for all channels (where applicable). Below is an example of the Instrument Configuration report as viewed using the Notepad utility.



```

InstrumentConfiguration.txt - Notepad
File Edit Format View Help

INSTRUMENT MODEL PARAMETERS
Number of channels : 1
Type of sensor : EC sensor
Gas type : 02
Meas. board serial number: 374
External pressure sensor: Disabled
Model name: 410/A/W1C00000
Installation type : wall mount instrument
Battery powered : Disabled
Option for nuclear application: Disabled
Display type: Black and white display
Analog output hardware type: Current analog output
Profibus DP: Disabled
Software version: 1.12

GENERAL CONFIGURATION
Measurement mode Continuous mode
Pressure unit [bar]
Temperature unit [°C]
Storage mode Rolling buffer
Storage RAM time 10 [s]
Storage FLASH time 3600 [s]
Autosave in flash Enabled

Channel 1
Medium Liquid
Gas unit ppm->ppb
Liquid 0
Resolution displayed 1
Alarms
Low Low Disabled 0.000000 [ppb]
Low Enabled 100.000000 [ppb]
High Enabled 10000.000000 [ppb]
High high Disabled 10000.000000 [ppb]
Hysteresis 5 [%]
Delay 15 [s]
Filter
State Disabled
Type Median
Depth 5
Central depth 3
Interference
CO2 or H2S H2S enabled
Chlorinity/salinity Salt enabled 19.000000 [g/l]
H2 Disabled 0.100000 [bar]

SOFTWARE KEY INFORMATION
Software Key : 14d9a4ed4f

LIQUID LIST
Water
Liquid density coefficients:
D[0] = 0.999840
D[1] = 0.000062
D[2] = -0.000008
D[3] = 0.000000
O2 Enabled
solubility coefficients:
S[0] = -12.080020
S[1] = 4358.264200
S[2] = -4.012150
  
```

8 Security Menu




Fig 8-1: Security Menu

Note:

When the instrument is started for the very first time, security is disabled by default. It is highly recommended that each user be entered into the system and given appropriate access rights as soon as possible to avoid any unauthorized access. Details of this process are described in this section.

8.1 Access Rights Management

Each user has a unique ID and user password. These ID and password are used by the software to:

- Allow or deny a user to perform an actions.
- To trace this action with his "ID" in a log file.

Once the ID and password are entered, the user is allowed to perform actions according to the "Access level" that has been attributed to his ID by the Manager. See ["Security Level Table" on page 100](#)

Table 8-1: Access levels

Level	Typical rights	Comments
0	View parameters, change views	Press the unlock button and OK to access
1	+ Start / Stop measurements	
2	+ Calibration	
3	+ Modify parameters	
4	+ Modify table "User $\leftrightarrow$ Access level" + Enable/Disable "Access right" features	There is at least one ID having the level 4

At startup, all the menus are locked. The user has to identify himself to get access beyond the different views (See ["Function Keys on the Header Bar" on page 26](#))

8.2 Configure Security

This enables defining the users with their access level when the software starts for the first time. It is possible to configure several parameters related to confidentiality. This requires a user access level 4.

Note:

Access rights are disabled by default.

- ▼ Access rights: When enabled, it is required to log in as a registered user (see ["User Management" on page 79](#)) to access the menus. When disabled (default), all menu are access free, and the effect of leaving the text box blank in user login window is that there will be no name recorded for the action in the log file.
- ☐ Enter a maximum session time in minutes for improved confidentiality. The user is logged out automatically when the set delay for inactivity is over.
- ▼ User action logging: When enabled, every action from a logged on user is recorded in a user log file for traceability.
- ⇒ Clear all user actions log file. Confirm to clear the log file. This functionality is aimed at clearing demo or test logs for example. The log file is a rolling buffer recording the past 100 actions.

8.3 User Management

Name	ID	Password	Level	
Armstrong	1007	1234	4	

OK Add Cancel

This window shows the list of registered users for the instrument. They are listed by name, ID, password and access level.

Note:

The "User password" must be at least 4 characters long.

Pressing on an empty line, or pressing the Add button brings a window to add a new user. Name, ID, password and access level (from 1 to 4) must be entered.

Add a collaborator

Name: Glenn

ID: 064532

Password: 2468

Level: 2

OK Cancel

Pressing on a registered user line brings a window for editing or deleting the user data in the list.

Note:

The list can contain up to 99 users

8.4 User Action Log File

Nbr	MM/dd hh:mm:ss	User ID	User Name
0	10/01 11:18:14		
1	10/01 11:04:08		
2	10/01 11:03:51		
3	10/01 10:59:51		
4	09/30 17:23:50		
5	09/30 16:55:18		
6	09/30 16:21:49		
7	09/30 16:16:18		
8	09/30 15:48:04		
9	09/30 15:09:15		

Cancel

Each time the user performs an important action, a record is written in the "User action log file". It is a rolling buffer which contains the last 100 user actions. The "User Interface" will allow viewing this log file (Menu Security / View log file). This log file contains the following data:

- line number
- the action name
- the user name and ID
- the current date and time.

Note:

Unsuccessful attempts to register are recorded in the log file without a user ID.

9 Products Menu




Fig 9-1: Products Menu

9.1 Overview

This option allows users to save and/or use previously saved product configurations. A maximum of 100 different product configurations can be stored in the instrument. The basic measurement configuration (gas to analyze, gas unit, alarm limits, analog outputs, etc.) can be set up for a product and will be automatically used by the instrument when that product is selected.

Product configurations can be moved from instrument to instrument if required. However, as the sensor only analyzes oxygen, only products configured to analyze oxygen can be selected on this instrument. Products configured to analyze other gases can, however, be set up on this instrument and easily transferred to other 410 or 510 instruments analyzing gases other than oxygen.

For ease of use, where product configurations are identical or similar, a **Copy** facility exists on the modify product screen. This enables copying a stored configuration and storing it in one or more additional locations. Then use the modify product option to identify and/or modify the duplicate configurations.

9.1.1 Select Product

Note:
If the PROFIBUS-DP communications protocol has been enabled, products can be selected for analysis using that facility (see “Input/Output Data” on page 66 and specifically “Change Product Command - Output” on page 68 for details).

- Select the product (0-99) to be analyzed (**oxygen gas analysis only**), or use the **Next** and **Previous** buttons to scroll sequentially through the existing product list. Alternatively, use the **Search** facility to search for a product. Enter a full or partial search criteria. If only one match is found, this product is automatically selected. If a number of products match the search criteria, then a list of matches will be displayed. Select a product directly from the list of matching products. Press **OK** to select the product or **Cancel** to exit.

9.1.2 Modify Product

- Select the product (index 0-99) to modify, or use the **Next** and **Previous** buttons to scroll sequentially through the existing product list. Alternatively, use the **Search** facility to search for a product. Enter a full or partial search criteria. If only one match is found, this product is automatically selected. If a number of products match the search criteria, then a list of matches will be displayed. Select a product directly from the list of matching products.
- Select the gas to analyze (up to three can be selected) from the drop down list. After selecting a product and gas, press **Configure** to configure the product.

- Configure the product as required (refer to “Measurement Configuration” on page 36 for additional information). Press **Analog out** to configure the analog outputs, **OK** to accept the configuration as is, or **Cancel** to exit.

- Configure the analog output as required (refer to “Channel Configuration” on page 52 for additional information). Press **OK** to accept the configuration, or **Cancel** to exit.

10 Global Configuration Menu




Fig 10-1: Global Configuration Menu

10.1 Overview

The global configuration option allows users to save, and use previously saved, instrument configurations. A maximum of 10 configurations can be saved, with configuration 0 (zero) the instrument default.

Once all the instrument parameters have been set up, use this option to save the configuration. Selecting pre-defined configurations avoids the need to re-enter all the parameters when using the instrument for a different application.

10.1.1 Save

The 'Save the current configuration' dialog box contains the following fields and buttons:

- Index:** A numeric input field with the value '2'.
- Name:** A text input field.
- Comment:** A text input field.
- Navigation buttons:** '<< Previous', 'Next >>', 'Save', and 'Cancel'.

- Define the index (1-9) to save the current configuration. Use the Next and Previous buttons to scroll sequentially through existing configurations, to overwrite an existing configuration or save as a new one.
- Enter a name to define the current configuration.
- Enter any comments to associate with this configuration.

10.1.2 Select

The 'Select a configuration' dialog box contains the following fields and buttons:

- Index:** A numeric input field with the value '0'.
- Name:** A text input field with the value 'Default configuration'.
- Comment:** A text input field.
- Navigation buttons:** '<< Previous', 'Next >>', 'Select', and 'Cancel'.

- Select the configuration (index 0-9) to use on the instrument.
Confirmation will be required for the selected configuration. The instrument must then be restarted (powered off and then back on) in order for the new configuration to take effect.

11 Services Menu




Fig 11-1: Services Menu - Part 1




Fig 11-2: Services Menu - Part 2

11.1 Sensor Diagnostics

11.1.1 Calibration Timer

The instrument can automatically remind the user when the next sensor calibration is due. This option is useful if you perform manual calibrations. However, if you have selected to automatically calibrate your instrument, this option should be disabled.

- ☐ To enable the timer, select enable and enter a delay in days.
- ▼ The display shows the current instrument date and time, next calibration due date and time, and the remaining days.

The next calibration date is updated when the sensor is calibrated. The event "Cal. required" is generated when the delay has elapsed.

11.1.2 Service Timer

The instrument can automatically remind the user when the next sensor service is due.

- ☐ Select enable and enter a delay in days. This should be validated by a level 3 user.

The display shows the current instrument date and time, the next sensor service due date and time, and the remaining days.

The next service date is updated when the button "Service done" is pressed after a service. The event "Service required" is generated when the delay has elapsed.

The sensor attached to your instrument will require periodic servicing and maintenance. For more information on this, please refer to the manual delivered with the sensor.


11.2 Language Selection

Check the language as required and restart the instrument to apply the change. The instrument will restart in the language selected

Note:

Level 3 or 4 is required to change the display language.


11.3 Clock



Type in each appropriate box the actual time and date, and select the display format for them.

11.4 Screen


11.4.1 Screen Calibration



This Windows CE screen allows you to adjust the click position corresponding to the displayed buttons. Use it if ever the sensitive areas are no longer properly aligned with the buttons on display. Follow the instruction given on screen:

Place the stylus right on the cross when asked and proceed. User will be asked to click on the screen to accept the new setting. If not, the new setting is not recorded and no change is made.

11.4.2 Screen Contrast




▼ Press the up or down arrow to increase or decrease the screen contrast. Press OK when finished.

Note:

This can also be called through the contrast icon on the main display.



11.5 Buzzer



Adjust the sounds available on the instrument:

When “screen tap” is enabled, a click sound is heard each time the screen is touched. The volume is adjustable.

The instrument alarm sound can be enabled or disabled to suit the application. The sound type and volume can also be adjusted.

Press the test button to test the adjustment made. Press again to stop.

11.6 Boards Info

11.6.1 Main Board Info

Main board info	
Model name	410/G/W1C00000
Software version	90.14
OS version	1.03
Instrument ID	00136A000134
Cancel	

For reference, this display gives information on the instrument model, software version and instrument ID.

11.6.2 Measurement Board Info

Measurement board info	
General	
Software version	104
Hardware version	1167B
Serial number	1
Model	Lum. G
Technical	
Ext. pressure option	No
Ana. outputs type	Current
Analog outputs corr. Amplifiers corr.	
Cancel	

For reference, this display gives information on the measurement board hardware and software.

Analog Outputs Correction Param.	
Output 1	
Slope	0.964760 [step/step]
Offset	1 [step]
Output 2	
Slope	1.000000 [step/step]
Offset	0 [step]
Output 3	
Slope	1.000000 [step/step]
Offset	0 [step]
Cancel	

Pressing the Analog output button displays for each channel the correction factor that is applied to the analogue outputs.

Amplifiers correction		
	Offset	Slope
I ref. led voltage	-0.028060	0.977440
I meas. led voltage	-0.028060	0.977440
Ref. phase amplitude	0.000000	1.000000
Meas. phase amplitude	0.000000	1.000000
Sensor temp.	-0.018890	0.974390
Temperature 1	-0.019380	0.968620
Temperature 2	-0.017930	0.967750
Ext. pressure	0.000000	1.000000
Cancel		


Pressing the amplifiers correction button displays the value of the actual correction factor on the amplifiers.

11.6.3 Sensor Parameters

Sensor parameters			
General			
Data version	1.00	A coeff.	-0.1
Serial	UNKNOWN	B coeff.	-0.0008
Smart sensor	No	C coeff.	0
Gas type	O2	D coeff.	6e-007
Spot	Power OT	Ksv coeff.	0.0404
PHI0	44.228 [°]	Tcal	25.1 [°C]
Temperature			
Th. alarm	Disabled	Slope	1.00
Th alarm val	-	Offset	0.00 [°C]
Advanced Param			
N°1	0.00009570		
N°2	0.01000000		
Cancel			

For reference this display gives information on the sensor model and type, last calibration, settings and behavior.

11.7 Batteries



This display gives the real time clock battery charge level and voltage.


11.8 Software Download



For Hach Ultra technician use only. Used when reloading the software for new versions.

Note:
This ends the application. User must stop and restart the instrument to restart the program.

11.9 End Application



Note:
This ends the application. User must stop and restart the instrument to restart the program.

12 Maintenance and Troubleshooting

12.1 Instrument Maintenance

Any instrument maintenance should be carried out by a qualified Hach Ultra Service Technician. Please contact your local representative should you feel any maintenance or instrument adjustments are required

12.2 Sensor Maintenance

The sensor spot needs to be replaced once a year. The procedure is very simple and takes no more than a few minutes.

12.2.1 Equipment Required

- Pair of tweezers and Maintenance tool - both supplied. Also available from kit no. 33022.
- Replacement sensor spot and O-ring - available from kit no. 33021

Note:

Check the Ksv factor of the new spot (value found on kit 33021 box). If this is different to the Ksv value displayed in the factory parameter (see [“Configure Manual Calibration”](#) on page 43) update the factory parameter to the new value.



12.2.2 Sensor Spot Removal

- 1) Using the tweezers, gently prise away the O-ring that secures the sensor spot.
- 2) Insert the narrow end of the maintenance tool over the sensor spot and gently squeeze to get a secure grip. Remove the spot.
- 3) The old sensor spot and O-ring can be discarded.



CAUTION:

Once the sensor spot is removed do not touch the inside of the sensor as this could scratch and damage the exposed sensitive measuring head (indicated with arrow).



12.2.3 Sensor Spot Replacement

- 1) Take the new sensor spot and place into the end of the sensor using the maintenance tool.



- 2) Using your fingers, put the new securing O-ring in place and push into position.



- 3) To ensure the O-ring is properly in place, take the maintenance tool and put the large end on top of the O-ring on the sensor. Push down firmly and twist left and right a few times until the O-ring is flush with the top of the sensor.



12.3 Storage, Handling and Transportation

Protect the instrument against the elements: rain, splashing, direct sunlight, etc.

A properly packaged instrument can be stored and transported at a temperature -20°C to +70°C and relative humidity up to 80%. Best practice for packing the instrument for transportation is to reuse the original packaging in which the instrument was first delivered. The instrument should be stored in suitable premises, free of dust, condensation and chemical evaporation.

In cold weather, avoid sudden temperature change (like when entering a warm room) and give the instrument enough time to adapt to the ambient temperature in order to avoid condensation inside.

To clean the instrument, wipe the housing clean with a cotton cloth or tissue. Always clean the instrument before storage. Pay attention not to scratch the surface of the display to retain good clarity over time.

CAUTION:

Never use liquids such as oil, benzene, solvents, or detergents for cleaning the instrument or sensor. A mild glass cleaner can be used to remove greasy stains.

12.4 Troubleshooting


The possible events, along with the text message displayed on the instrument numeric view screen, the reason for the event and its criticality are listed in [Table 12-1, “List of Events,” on page 94](#). An event is something which affects the measurement. In the numeric view, the current events are indicated with the gas concentration at the same place.

Note:


Pressing , , or  gives explanation about the event.

Whenever an abnormal event is met, a sign is displayed on the upper left of the screen. Pressing on the sign calls a window giving further details about the actual situation.


There are three levels of abnormal conditions:



- **Alarm** - There is a severe problem causing the channel to be out of action, and the system alarm relay to be enabled



- **Warning** - Events less critical than a system alarm (e.g. measurement alarm)



- **Information** - For information only; no action is required

Note:

Use the Diagnostic view for troubleshooting. See [“Sensor Diagnostics” on page 87](#)

12.5 List of Events and Alarms

Table 12-1: List of Events

Event type	Name	Description	Bit mask value (32 bits long)
Information 	Measure	Normal measurement mode.	0x00000000
	Filter enabled	The gas measurements are filtered.	0x00000001
	Sample measurement	The sample measurement is started.	0x00000002
	Sample measurement aborted by user	The sample measurement has been stopped manually.	0x00010000
	Sample measurement aborted by time-out	The sample measurement has stopped as the maximum time to measure a sample has been exceeded.	0x00020000
	Sample measurement aborted by sensor error	The sample measurement has stopped due to an error during the measurement.	0x00040000
Warning 	Alarm snooze	The alarm snooze is ON.	0x00000004
	Calibration	Channel in calibration.	0x00000008
	Alarm low low	Gas concentration below the Alarm LowLow limit.	0x00000010
	Alarm low	Gas concentration is below the Alarm Low limit.	0x00000020
	Alarm high	Gas concentration is above the Alarm High limit.	0x00000040
	Alarm high high	Gas concentration is above Alarm HighHigh limit.	0x00000080
	Calibration required	A calibration of the sensor is required.	0x00000100
	Service required	The sensor requires a service.	0x00000200
	Channel on hold	Channel on hold during calibration.	0x00400000
	Low level zero calibration gas	The level of zero calibration gas is very low.	0x04000000
	Auto calibration required	An automatic sensor calibration is due.	0x10000000
	Auto calibration in progress	An automatic sensor calibration is in progress.	0x20000000
	Auto calibration failed	The automatic sensor calibration has failed.	0x40000000
Alarm 	Channel disabled	The channel has been disabled.	0x00000400
	Channel out	The measurement board has been disconnected (or does not answer).	0x00000800
	Sensor out	The sensor has been disconnected.	0x00001000
	External pressure sensor out	The external pressure sensor has been disconnected	0x00002000
	Thermal cut-off	The thermal cut-off value has been exceeded	0x00004000
	Profibus-DP	The PROFIBUS-DP module has not received any measurements from the instrument for 30 secs.	0x00080000

13 Specifications

13.1 General Principle of Operation

Optical sensing of oxygen originates from the work of Kautsky in 1939 where he demonstrated that oxygen can dynamically quench the fluorescence of an indicator (decrease the quantum yield). This principle has been reported in various fields of application such as monitoring aquatic biology in waste water, tests for blood gas analysis and cell culture monitoring. The method is now recognized by ASTM (American Society for Testing and Materials) for the measurement of oxygen in water. Compared to classical oxygen detection using electrochemical sensors, luminescent technology offers several advantages such as no oxygen consumption, independence from sample flow velocity, no electrolyte and low maintenance.

Optical sensing of oxygen is based on the measurement of the red fluorescence of a dye/indicator illuminated with a blue light as shown in Fig 13-1.




Fig 13-1: Principle of Optical Oxygen Detection Using Fluorescent Dye

The dye fluorescence is quenched by the presence of oxygen. The oxygen concentration can be calculated by measuring the decay time of the fluorescence intensity as shown by Fig 13-2 left. The higher the oxygen concentration is, the shorter the decay time will be. By modulating the excitation, the decay time is transformed into a phase-shift of the modulated fluorescence signal, which is independent of fluorescent intensity and thus of potential aging (Fig 13-2 right).




Fig 13-2: Fluorescence Decay Time (left) and Modulated Signals (right)

The oxygen partial pressure (pO_2) is then linked to the corresponding phase-shift measurement (Φ) to build the sensor calibration curve (shown right in Fig 13-3 below). This curve is described by the Stern-Volmer equation (shown left in Fig 13-3 below) where K_{sv} is the indicator quenching constant (in $mbar^{-1}$) representing the quenching efficiency of the oxygen and thus the sensor sensitivity, f_0 is a constant and Φ_0 is the phase-shift at zero oxygen representing the unquenched fluorescence decay time of the dye. The calibration curve thus relies on two parameters: the phase-shift at zero oxygen and the luminescent spot sensitivity, K_{sv} . The dissolved oxygen concentration is then calculated with Henry's law using the water solubility curve as a function of the temperature.




Fig 13-3: Stern-Volmer Equation and Calibration Curve

13.2 Hardware Description

The instrument hardware is made of one main board, and one measurement board for the measurement channel (= the sensor).

The main board includes the controls for power, display, the touch screen, the barometric sensor, the alarms, and communication ports. The measurement board performs measurements and executes commands from the main board. It holds the "Analog output" and "Relays" that send information to external systems.

A hardware watchdog is activated at program start up, to check that the system is not frozen (i.e. infinite loop, system crash, etc.). If the watchdog is not refreshed by the software every minute, the measurement display, the relays and the analog output are frozen up to 2 minutes. Then the reset shuts down the instrument for 10 seconds and the start-up procedure is performed. At the same time all the hardware (sensor, measurement board) are reset.

13.3 Model Identification System

The analyzer identification number and the instrument serial number are located on the label on the back panel, and can be found on order confirmation and invoice papers.

Complete systems can be ordered through a single Part Number as described in the following matrix:

410 Model Number Matrix

W Wall			
P Panel			
6 6 mm Sample Inlet			
4 ¼" Sample Inlet			
0 RS-485			
1 PROFIBUS-DP / RS-485			
0 Standard			
J Japanese language			
K Korean language			
C Chinese language			

4	1	G	1	-				
----------	----------	----------	----------	----------	--	--	--	--

Example:

41G1 - W400

- Analyzer model 410 for oxygen measurement with luminescent sensor
- Wall mounted
- ¼" Sample Inlet
- RS-485
- Standard software (English, French, German, Italian and Spanish languages)

Each system includes a 410 transmitter, a G1100 sensor, a fully equipped flow-chamber (G1100-Fx), a pressure reducer (33015) for the calibration bottle, a spares kit (33021) and a tools kit (33022).

Orbisphere 410 instruments and G1100 sensors and accessories are also available as individual items that can be ordered separately.

13.4 Operating Conditions

Operating temperature limits	-5°C to +50°C
Storage temperature limits	-20°C to +70°C
Operating humidity limits	0 to 95% non condensing relative humidity
Operating altitude	From 0 to 2,000 m. (6,550 ft.) above sea level
EMC requirements	EN61326:1997 /A1:1998 /A2:2001 /A3:2003 CAUTION: <i>The wall mount instrument is a Class A product. In a domestic environment this product may cause radio interference in which case the user may be required to take adequate measures.</i>
Safety requirements	EN61010-1: 2001 Directive 73/23/EEC
Enclosure ratings	IP 65 Totally protected against dust. Protected against low pressure jets of water from all directions.

13.5 Measurement

Range	0 to 20,000 ppb
Repeatability (r^{95})	± 1 ppb $\pm 2\%$ in the 0 to 600 ppb range
Reproducibility	± 2 ppb $\pm 2.5\%$ in the 0 to 600 ppb range
Accuracy	± 2 ppb $\pm 2.5\%$ in the 0 to 600 ppb range (indicative $\pm 15\%$ in the ppm range)
Lowest detection limit	2 ppb
Response time (90%)	30 seconds
Display resolution	0.1 ppb
Calibration	Fully automatic user programmable single point zero calibration
Verification	Fully automatic user programmable single point zero verification
Calibration sample	Standard 99.999% N ₂ (quality 50) gas bottles with 5/8" x 18 (C10) connection. Ask your local HACH ULTRA representative for advice on local suppliers. Dedicated pressure regulator is available from HACH ULTRA

13.6 Power Supply

Universal 100 VAC to 240 VAC @ 50/60Hz - 25VA
10 to 30 VDC - 25W

13.7 Communication

- RS-485 or PROFIBUS-DP (optional)
- USB client
- USB host
- Ethernet 10/100 Base-T

13.8 Size and Weight

Instrument version	Height [mm] <i>inches</i>	Depth [mm] <i>inches</i>	Width [mm] <i>inches</i>	Weight (kg) <i>pounds</i>
Wall or pipe mount	236.5 9.31"	160 6.30"	250 9.84"	3.8 8.38 lbs
Panel mount: Face (housing)	156 (123) 6.14" (4.84")	250 9.84"	220 (214) 8.86" (8.43")	2.9 6.39 lbs

13.9 Analog and Digital Outputs

Analog output	
Analog current output version on the measurement board	4-20 mA (default) or 0-20 mA (configuration with software) • 3 configurable outputs • Maximum load: 500 ohm • Sensitivity: 20µA • Accuracy: $\pm 0.5\%$ (between operating temperature limits)
Analog voltage output version on the measurement board	0- 5 V output (hardware option) • 3 configurable outputs • Minimum load: 10 KOhm • Sensitivity: 5 mV • Accuracy: $\pm 0.5\%$ (between operating temperature limits)
Digital outputs	
Measurement alarm relays on the measurement board	Three alarm relays 2A-30 VAC or 0.5A-50 VDC on a resistance load Configurable to Normally Open [NO] or Normally Closed [NC] contacts by changing the jumper positions.  WARNING Connect only safety low voltage <33 VAC RMS
System alarm relay on the main board	One "instrument system alarm" relay per instrument 2A-30 VAC or 0.5A-50 VDC on a resistance load Normally closed [NC] (NO relay also available) when instrument is turned on. Opens when a system alarm is detected, and when it does not receive any signal.  WARNING Connect only safety low voltage <33 VAC RMS

13.10 Security Level Table

A cross means that the user who has this user security level can access this function or setting (See “User Management” on page 79).

Note:

When not shown, the sub-levels carry the same security level as the level above.

Main	0	1	2	3	4
View	X	X	X	X	X
Measurement	X	X	X	X	X
Calibration			X	X	X
Inputs/outputs			X	X	X
Communication				X	X
Security				X	X
Products			X	X	X
Global config				X	X
Services				X	X

View	0	1	2	3	4
Numeric	X	X	X	X	X
Graphic	X	X	X	X	X
Statistical	X	X	X	X	X
Event	X	X	X	X	X
Diagnostics	X	X	X	X	X
Configure				X	X

Measurement	0	1	2	3	4
Config instrument				X	X
Config channel				X	X
Measurement file				X	X

Calibration	0	1	2	3	4
Gas sensor			X	X	X
Barometer			X	X	X
Reports			X	X	X

Inputs/Outputs	0	1	2	3	4
Snooze				X	X
View				X	X
Relays				X	X
Analog outputs				X	X

Communication	0	1	2	3	4
RS 485				X	X
RS 485 simple				X	X
Profibus DP				X	X
Modbus				X	X
USB-A				X	X
HTTP / TCP/IP				X	X

Security	0	1	2	3	4
Configuration					X
Access table					X
View log file				X	X

Products	0	1	2	3	4
Select product			X	X	X
Modify product				X	X

Global config	0	1	2	3	4
Save config				X	X
Select config				X	X

Services	0	1	2	3	4
Diagnostics				X	X
Language				X	X
Clock				X	X
Screen				X	X
Buzzer				X	X
Boards info				X	X
Batteries				X	X
Soft download					X
More					X

Gas sensor	0	1	2	3	4
Calibration			X	X	X
Verification			X	X	X
Configuration				X	X
Reports			X	X	X

Reports	0	1	2	3	4
Sensor chan 1			X	X	X
Interf. chan 1			X	X	X
Barometer			X	X	X

Diagram Legend:					
Security level :	0	1	2	3	4
Available			X	X	X
Optional				X	X
Not available today				X	X

Note:

For the USB-A option in the Communication Menu, level 4 access is required to import the access table data.

13.11 Default Parameters

The table below indicates the factory default configurations. The instrument has these settings when started for the first time.

Parameter	Default settings	Customer settings
Security	Disabled	
Measurement		
• Measurement mode	Continuous	
• Data filter	Disabled	
• Sample phase	Liquid	
• Units	ppm-ppb	
• Display resolution	XXX	
• Storage mode	Rolling buffer	
Temp unit	°C	
Pressure unit	bar	
Calibration		
• Mode	Zero calibration	
• Hold	Enabled	
• Auto-end	Enabled	
Analog outputs		
• Range	4-20 mA (0-5V)	
• Outputs	Gas measurement	
• Extended mode	Disabled	
• Characteristics	Monolinear mode	
Alarm relays	Disabled	
Thermal cutoff	Enabled	
• Thermal cutoff temp	65°C	
Calibration timer	Disabled	
Service timer	Disabled	
Buzzer		
• Screen tap	Enabled	
• Alarm sound	Disabled	
Display		
• Minigraph	Enabled	
• Temperature	Disabled	

14 Part Lists

14.1 Accessories and Spare Parts

Part N°	Description
32959	Converter RS232/RS-485. Battery powered; batteries not included
32963	Wall mounting kit
32964	Panel mounting kit
32965	Locking key for wall instruments
32970	Cap to protect USB connector
32972	Pipe mounting kit for wall instrument
32973	PROFIBUS-DP upgrade kit (includes board and software key)
32975	Power supply connector (10-30 VDC) for panel and wall instruments
33015	Pressure reducer for calibration gas bottles with 0.1 l/min flow, 5/8" x 18 connection, max 70 bar
33016	Solenoid valve + connector for G1100-Fx flow chambers
33017	Cap for 33016 valve (incl. Cable)
33018	Delrin flow chamber support for G1100-Fx
33019	Flow cell for G1100-Fx flow chamber assemblies
33020	O-ring for G1100-Fx flow chambers
33021	G1100 sensors spot and O-rings kit for 2 years operation
33022	Tool kit for G1x00 sensors
32531.03	Ethernet cable for wall and panel instruments including connectors, length = 3m
32531.10	Ethernet cable for wall and panel instruments including connectors, total length = 10 meters
32531.20	Ethernet cable for wall and panel instruments including connectors, total length = 20 meters
32533.03	USB client cable including connectors, length = 3m
32534.03	PROFIBUS-DP cable including SUB-D 9 female connector (length = 3m)
32534.MM	PROFIBUS-DP cable including SUB-D 9 female connector, total length = MM, price added per meter of length greater than 3 m.
G1100-300	Luminescent oxygen sensor for pure water applications, with 3 m cable
G1100-F4	Complete flow chamber for G1x00 sensors, 1/4 inch fittings
G1100-F6	Complete flow chamber for G1x00 sensors, 6 mm fittings

14.2 Instrument Options

A number of differently configured 410 instruments are available for use with the G1100 Sensor. The different models available are described in the following matrix.

410 Model Number Matrix

G G1100 oxygen sensor									
W Wall									
P Panel									
1 100-240 VAC									
2 10-30 VDC									
C 0/4-20 mA									
0 RS-485									
1 PROFIBUS-DP / RS-485									
0 Standard									
J Japanese language									
K Korean language									
C Chinese language									
4	1	0	/	G	/			C	
								0	0
								0	0

Example 410 / G / W1C00000

- Analyzer model 410
- Measuring oxygen with a G1100 sensor
- Wall mounted
- 100-240 VAC
- 0/4-20 mA analog output
- RS-485
- Standard software (English, French, German, Italian and Spanish languages)

Appendix A: Glossary

A.1 Gas Units

Table A-1: Gas Units

Unit	Meaning
% air	percentage, by weight. A concentration of 100% air corresponds to liquid saturated with air at current pressure and temperature. The equivalent concentration of O ₂ is approximately 20% O ₂ in normal conditions.
% O ₂	percentage, by weight. A concentration of 100% O ₂ corresponds to liquid saturated with pure O ₂ at current pressure and temperature.
%Vbar	ratio in percent between the partial pressure of gas measured and the atmospheric pressure
%Vext	ratio in percent between the partial pressure of gas measured and the external pressure. Available when an external pressure sensor is present.
µg/L	micrograms per liter
atm	atmosphere
bar, mbar	bar, millibar
cc/kg	volume of gas per kg of liquid. The volume of gas is calculated considering normal conditions (T = 0°C, p = 1atm)
g/kg	grams per kilogram
g/m ³	grams per cubic meter
mg/L	milligrams per liter
ml/L	milliliters per liter
Pa, hPa, kPa	Pascal, hecto Pascal, kilo Pascal
ppb	parts per billion, by weight
ppm	parts per million, by weight (same as mg/kg)
ppm Vb	parts per million, per volume, barometric pressure referenced. = %Vbar / 10,000
ppm Ve	parts per million, per volume, external pressure referenced. = %Vext / 10,000
psia	pound per square inch, absolute
V / V	volume per volume (ratio)

A.2 Generic Terms and Definitions

Table A-2: Generic Terms and Definitions

Terms	Meaning
Absolute pressure	This is the total pressure in a system (i.e. relative pressure, plus atmospheric pressure)
Analog output	A voltage or current signal that is a continuous function of the measured parameter.
ASCII	American Standard Code for Information Interchange. A standard character-coding scheme used by most computers to display letters, digits and special characters.
Baud rate	Baud rate means transmission speed (Unit: bits per second, bps), especially for RS-232/422/485 interfaces.
CIP	Cleaning In Progress
Concentration	The relative content of a component in a gaseous or liquid media.
Conductivity	The reciprocal of electrical resistivity.
FIFO (First In First Out)	FIFO is a concept to describe the behavior of a buffer. It means the data which entered first will exit first.
Headspace	The empty volume above a liquid or solid in a closed container.
Master / Slave modes	A device operating as a master will poll one or more devices operating as a slave. This means a slave device cannot volunteer information; it must wait to be asked for it.
Parallel communication	Parallel communication represents a connection in a computer system in which the bits of a byte are transmitted over separate channels at the same time.
PLC	Programmable Logic Controller. It communicates with other process control components through data links. It is used in process control for simple switching tasks, PID control, complex data manipulation, arithmetic operations, timing and process and machine control.
PROFIBUS-DP	The PROFIBUS-DP (Decentralized Peripheral) fieldbus is designed especially for communication between automation control systems and distributed I/O at the device level. Each DP device has specific parameters such as device version, baud rate, data format, I/O length, user parameters, etc. These parameters are stored in a file with .GSD extension.
PROFIBUS-DP GSD files	The GSD file is provided by the manufacturer and is required for device configuration. A GSD file is a readable ASCII text file that contains both general and device-specific specifications for communication (Communication Feature List) and network configuration.
Relative pressure	Relative pressure is the over pressure in a system (i.e. absolute pressure less atmospheric pressure). This is the customary gauge reading.
Resistivity	The opposition offered by a body or substance to the passage through it of a steady electric current.

Table A-2: Generic Terms and Definitions

RS-232	RS-232 is a serial communication standard providing asynchronous communication capabilities with hardware flow control, software flow control, and parity check. Maximum transmission distance is up to 15 meters at a max. 20,000 bps. A converter is required to interface RS-232 with RS-422 or RS-485.
RS-422	RS-422 is intended for point-to-point communications. It provides much longer transmission distance but less signal line compares to RS-232. RS-422 adopts differential transmission technology and thus provides high-speed transmission up to 10mbps and maximum transmission distance up to 1.2km/110kbps.
RS-485	RS-485 is an enhanced version of RS-422 and is used for multipoint communications, meaning that many devices may be connected to a single signal cable. It is compatible to RS-422 interface and provides 2 wire bus topology.
Serial communication	Serial communication represents a connection in a computer system in which the bits of a byte are transmitted sequentially over a single wire.
Single twisted pair	In this version, all devices are connected to a single Twisted Pair. Thus, all of them must have drivers with tri-state outputs (including the Master). Communication goes over the single line in both directions. It is important to prevent more devices from transmitting at once (software problem).
USB	Universal Serial Bus. An external peripheral interface standard for communication between a computer and external peripherals over a cable using bi-serial transmission. The USB host uses a type A connector, and the USB peripheral uses a type B connector.

Annex

Tables and Illustrations

Fig. 1-1	Wall/Pipe Mount Instrument Dimensions (in millimeters)	10
Fig. 1-2	Wall Mount Bracket	11
Fig. 1-3	Pipe Mount Diagram	11
Fig. 1-4	Wall and Pipe Mount Connection Panel	12
Fig. 1-5	Panel Mount Instrument Dimensions (in millimeters)	13
Fig. 1-6	Panel Mount Bracket Frame	14
Fig. 1-7	Opening Dimensions	14
Fig. 1-8	Panel Mount Connection Panel	15
Fig. 1-9	USB-B Adapter Cable	17
Fig. 1-10	FIXCON® Connector	17
Fig. 1-11	Main Board	19
Fig. 1-12	Connector P8	19
Fig. 1-13	Connector P3	19
Fig. 1-14	Measurement Board	20
Fig. 1-15	Connector J7	20
Fig. 1-16	Output Relays	20
Fig. 1-17	Sensor Cables Attached to a Wall Mount Instrument	21
Fig. 1-18	Flow Chamber Dimensions and Components	22
Fig. 2-1	Numeric View	25
Fig. 2-2	Main Menu Window	27
Fig. 2-3	Rolling List Example	27
Fig. 2-4	Virtual Editing Keyboard	27
Fig. 2-5	Identification Window	28
Fig. 2-6	Warnings	28
Fig. 2-7	Main Menu Structure	29
Fig. 3-1	View Menu	31
Fig. 3-2	Skewness	33
Fig. 3-3	Kurtosis	33
Fig. 4-1	Measurement Menu	35
Fig. 4-2	Alarms System Diagram	37
Fig. 5-1	Calibration Menu	39
Fig. 6-1	Inputs/Outputs Menu	47
Fig. 6-2	Analog Outputs Menu	50
Table 6-1	Extended Event Table	53
Fig. 6-3	"Linear" Characteristics Diagram	56
Fig. 6-4	"Tri-linear" Characteristics Diagram (4-20 mA shown)	57
Fig. 7-1	Communication Menu	59
Fig. 8-1	Security Menu	77
Table 8-1	Access levels	78
Fig. 9-1	Products Menu	81
Fig. 10-1	Global Configuration Menu	83
Fig. 11-1	Services Menu - Part 1	85
Fig. 11-2	Services Menu - Part 2	86
Table 12-1	List of Events	94
Fig. 13-1	Principle of Optical Oxygen Detection Using Fluorescent Dye	95
Fig. 13-2	Fluorescence Decay Time (left) and Modulated Signals (right)	95
Fig. 13-3	Stern-Volmer Equation and Calibration Curve	96

Table A-1 Gas Units105

Table A-2 Generic Terms and Definitions106

User Notes

[illegible]

Global Headquarters

6, route de Compois, C.P. 212,
1222 Vérenaz, Geneva, Switzerland

Tel ++ 41 (0)22 594 64 00

Fax ++ 41 (0)22 594 64 99

Americas Headquarters

481 California Avenue,
Grants Pass, Oregon 97526, USA

Tel 1 800 866 7889 / 1 541 472 6500

Fax 1 541 479 3057

www.hachultra.com

